

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21006525/R1QF3Q2
Date: 16/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070059496
Claimant Vehicle No :	XE8885A	Insured Vehicle No :	GBF9421D
Date of Loss:	18/05/2021	Nature of Claim:	TP
		Claim No:	8402465218SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE8885A	Engine No:	GH11745979
Make & Model:	UD TRUCKS ESCOT V, 10.8 D GKB5ELDHNT (M)	Chassis No:	JNCM1F1A7HU025162
Reg. Date:	15/09/2017 (Man. Year: 2017)	Odometer:	236133 km
Colour:	Blue		
Engine Capacity:	10837 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

6/16/2021

Adjuster Report

Date of Assignment: 09/06/2021

Date Inspected: 09/06/2021

Inspected At:

R&s Engineering Works Pte Ltd (HQ)
13 PIONEER SECTOR 1
Singapore 628424

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/16/2021

Adjuster Report

MARKET VALUE:\$101,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Bent	0.00 F	*- F
2	1		*FRT BUMPER UPPER STOP	Cut	0.00 F	*- F
3	1		*FRT BUMPER GARNISH	Cracked	0.00 F	*- F
4	1		*FRT BUMPER BRACKET SIDE LH	Bent	0.00 F	*- F
5	1		*FRT BUMPER SIGNAL LAMP LH	Cracked	0.00 F	*- F
6	1		*FRT LH BUMPER FOG LAMP	Scratched	0.00 F	*- F
7	1		*FRT PANEL	Deformed	0.00 F	*- F
8	1		*FRT PANEL GARNISH HANDLE	Scratched	0.00 F	*- F
9	1		*FRT CORNER PANEL LH	Cut	0.00 F	*- F
10	1		*FRT LH HEADLAMP ASSY	Scratched	0.00 F	*- F
11	1		*FRT STEP PANEL TOP GARNISH LH	Cracked	0.00 F	*- F
12	1		*WIPER WASHER TANK	Deformed	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >