

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006535/NPA3Q2**Date:** 11/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800045889
Claimant Vehicle No :	SLE5502S	Insured Vehicle No :	SLZ3017D
Date of Loss:	07/06/2021	Nature of Claim:	TP
		Claim No:	5227294280SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE5502S	Engine No:	L15B3535445
Make & Model:	HONDA SHUTTLE, 1.5 G CVT ABS (A)	Chassis No:	GK81004643
Reg. Date:	26/07/2016 (Man. Year: 2016)	Odometer:	83760 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Neuton 5 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Neuton 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,861.68	6,667.56	5,194.12	43.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,550.00	1,320.00	4,230.00	76.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,411.68	7,987.56	9,424.12	54.13
Approved Total (Overridden) (S\$)		6,400.00		
(S\$)	17,411.68	6,400.00	11,011.68	63.24
+ GST 7.00/7.00% (S\$)	1,218.82	448.00	770.82	63.24
Nett Amount (S\$)	18,630.50	6,848.00	11,782.50	63.24
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,283.45		
Global Sum Settlement (S\$)		7,280.00		

INSPECTION

Date of Assignment:	09/06/2021		
Date Inspected:	09/06/2021	Inspected At:	AP Automotive Services Pte Ltd (HQ) Blk 9006 Tampines Street 93, #01-202 Singapore 528840
Estimated Period of Repair:	4.0 days		

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	801.00 FL	*600.00 FL
2	1		*BONNET LOCK	Serviceable	136.00 FL	*- FL
3	2		*BONNET HINGE L+R	Serviceable	51.00 FL	*- FL
4	2		*HEADLAMP L+R	Cracked	4,478.00 FL	*2,600.00 FL
5	2		*HEADLAMP BRACKET L+R	Deformed	104.00 FL	*104.00 FL
6	1		*FRONT GRILLE	Cracked	253.00 FL	*253.00 FL
7	1		*FRONT GRILLE CHROME	Cracked	255.00 FL	*255.00 FL
8	1		*FRONT GRILLE LOGO -HONDA	Necessary	35.00 FL	*35.00 FL
9	1		*FRONT BUMPER	Cracked	945.00 FL	*750.00 FL
10	1		*FRONT BUMPER GRILLE	Cracked	120.00 FL	*120.00 FL
11	1		*FRONT BUMPER FOG LAMP GARNISH L+R	Cracked	258.00 FL	*258.00 FL
12	1		*FRONT BUMPER TOWING COVER	Serviceable	36.00 FL	*- FL
13	2		*FRONT BUMPER RETAINER L+R	Cracked	66.00 FL	*66.00 FL
14	1		*FRONT BUMPER REINFORCEMENT BAR	Dented	346.00 FL	*346.00 FL
15	1		*FRONT BUMPER UNDERCOVER	Deformed	158.90 FL	*158.90 FL
16	2		*FRONT FENDER L+R	Serviceable	944.60 FL	*- FL
17	2		*FRONT FENDER TOP GARNISH L+R	Serviceable	128.10 FL	*- FL
18	2		*FRONT FENDER WINDOW MOULDING L+R	Serviceable	302.90 FL	*- FL
19	2		*FRONT FENDER COWLING L+R	Cracked	211.80 FL	*211.80 FL
20	1		*FRONT SUPPORT PANEL	Dented	567.80 FL	*400.00 FL
21	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed	82.00 FL	*82.00 FL
22	1		*AIRCON CONDENSOR	Dented	866.00 FL	*500.00 FL
23	2		*AIRCON CONDENSOR AIRGUIDE L+R	Deformed	96.00 FL	*96.00 FL
24	1		*RADIATOR	Bent	700.00 FL	*700.00 FL
25	2		*RADIATOR FAN COWLING	Deformed	270.00 FL	*180.00 FL
26	2		*RADIATOR FAN BLADE	Serviceable	96.00 FL	*- FL
27	2		*RADIATOR FAN MOTOR	Not Working	594.00 FL	*240.00 FL
28	1		*SUCTION PIPE	Serviceable	296.00 FL	*- FL
29	1		*DISCHARGE PIPE	Serviceable	287.00 FL	*- FL
30	1		*FRONT HORN	Deformed	72.00 FL	*40.00 FL
31	1		*RADIATOR TANK	Deformed	45.00 FL	*45.00 FL
32	1		*WIPER WASHER TANK (NPA)	Serviceable	0.00 FL	*- FL
33	1		*BONNET INSULATOR CLIPS	Not Necessary	100.00 FS	*- FS
34	1		*FRONT NUMBER PLATE	Dented	120.00 FS	*55.00 FS
35	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
36	2		*FRONT FENDER COWLING CLIPS	Not Necessary	200.00 FS	*- FS
37	2		*FRONT FENDER QUARTER WINDOW SEALANT	Not Necessary	240.00 FS	*- FS
38	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*50.00 FS
39	1		*RADIATOR COOLANT	Necessary	120.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,582.10	8,275.70
- List Item Discount on L Items 20.00/20.00% (S\$)	2,720.42	1,608.14
Total Parts (S\$)	11,861.68	6,667.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	500.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	500.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
4	TO RNR INNER TRIM AND UPHOLSTERY	New	400.00	0.00
5	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS	New	300.00	120.00
6	TO RNR FRONT RADIATOR	New	250.00	50.00
7	TO CHECK WATER LEAK	New	150.00	20.00
8	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	800.00	0.00
9	TO PERFORM RUST PROOFING	New	400.00	80.00
10	TO RNR HORN AND TEST FUNCTION	New	150.00	20.00
11	TO RNR FRONT QAURTER WINDOW	New	150.00	0.00
Gross Labour Cost (\$\$)			5,550.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >