

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
Soh Ching Chye		Cust No/Name /Soh Ching Chye	
9 Rivervale Crescent		Reg No/Reg Date SGZ3300U / 24/01/2017	
#12-29		Date In/Mileage 04/06/2021/ 0	
Singapore 545086		Chassis No VF73ABHZTGJ811723	
Contact No Mobile: 81611180		Engine No 10JBHD3064541	
		Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML	
		Colour/Trim EUM SABLE / IXF YATAGO GREY	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	04/06/2021/ 16:40	QUK	282 / Kevin Leong	16595

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LINK	1.00	146.00	0.00	146.00
M MOUNTING BRACKET LH	1.00	299.00	0.00	299.00
M RADIATOR NEW	1.00	686.00	0.00	686.00
M FIXING BRACKET	2.00	19.00	0.00	38.00
M FIXING BRACKET	2.00	21.00	0.00	42.00
M MOTOR-DRIVEN FAN	1.00	516.00	0.00	516.00
M FAN CONTROL	1.00	150.00	0.00	150.00
M DEGASSING TANK	1.00	98.00	0.00	98.00
M EXH MANIFOLD	1.00	486.00	0.00	486.00
M EXH MANIF GASK	1.00	56.00	0.00	56.00
M CATALYST MUFFLER TR PSA K732	1.00	2223.00	0.00	2223.00
M FIXING CLAMP DIAM 64,5	1.00	26.00	0.00	26.00
M DISTRIBUTOR CHAMBER	1.00	840.00	0.00	840.00
M DIST CHB BRACKET	1.00	43.00	0.00	43.00
M DIST CHB BRACKET	1.00	43.00	0.00	43.00
M DIST CHB BRACKET	1.00	43.00	0.00	43.00
M AIR HOSE	1.00	75.00	0.00	75.00
M HOSE SEAL	1.00	13.00	0.00	13.00
M AIR UNION	1.00	94.00	0.00	94.00
M AIR UNION	1.00	121.00	0.00	121.00
M TURBO NEW	1.00	2448.00	0.00	2448.00
M END-SCREW GASKET 16,8X12,5 EP 1	4.00	7.00	0.00	28.00
M TUBE SEAL	1.00	5.00	0.00	5.00
M TURBO GASKET	1.00	6.00	0.00	6.00
M OIL RETURN PIPE	1.00	100.00	0.00	100.00
M TURBO LUBE PIPE	1.00	139.00	0.00	139.00
M FRONT BUMPER	1.00	1031.00	0.00	1031.00
M BUMPER BRACKET	1.00	330.00	0.00	330.00
M BUMPER MOULDING	1.00	207.00	0.00	207.00
M BUMPER MOULDING	1.00	207.00	0.00	207.00
M BUMPER MOULDING	1.00	227.00	0.00	227.00
M BUMPER RUBBER BOOT	1.00	308.00	0.00	308.00
M GUARD GRILLE INFERIEUR	1.00	311.00	0.00	311.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Soh Ching Chye	Cust No/Name /Soh Ching Chye
9 Rivervale Crescent	Reg No/Reg Date SGZ3300U / 24/01/2017
#12-29	Date In/Mileage 04/06/2021/ 0
Singapore 545086	Chassis No VF73ABHZTGJ811723
Contact No Mobile: 81611180	Engine No 10JBHD3064541
	Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML
	Colour/Trim EUM SABLE / IXF YATAGO GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	04/06/2021/ 16:40	QUK	282 / Kevin Leong	16595

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BADGE SUPPORT	1.00	205.00	0.00	205.00
M CHEVRON EMBLEM SUPERIEUR	1.00	161.00	0.00	161.00
M CHEVRON EMBLEM INFERIEUR	1.00	161.00	0.00	161.00
M BRACKET SET	1.00	125.00	0.00	125.00
M BUMPER MOULDING	1.00	173.00	0.00	173.00
M BRACKET SET LAT	1.00	125.00	0.00	125.00
M RECESS DOOR	1.00	71.00	0.00	71.00
M ABSORBERS SET	1.00	92.00	0.00	92.00
M BUMPER BRACKET	1.00	516.00	0.00	516.00
M BUMPER BRACKET	1.00	224.00	0.00	224.00
M PLUG LH	1.00	96.00	0.00	96.00
M REAR DUCT RH	1.00	119.00	0.00	119.00
M REPAIR SET	1.00	92.00	0.00	92.00
M FACE CROSSMEMBR SUP	1.00	261.00	0.00	261.00
M FACE CROSSMEMBR INF ASS	1.00	80.00	0.00	80.00
M ABSORBERS SET	1.00	92.00	0.00	92.00
M AIR BULKHEAD LH	1.00	108.00	0.00	108.00
M AIR BULKHEAD RH	1.00	108.00	0.00	108.00
M AIR BULKHEAD	1.00	154.00	0.00	154.00
M BRACKET CROSSME LH ASS	1.00	196.00	0.00	196.00
M BRACKET CROSSME RH ASS	1.00	197.00	0.00	197.00
M FACING SUPPORT LH ASS	1.00	90.00	0.00	90.00
M FACING SUPPORT RH ASS	1.00	80.00	0.00	80.00
M FR MIN BPR FIX	1.00	252.00	0.00	252.00
M FRONT WING LH ASS	1.00	571.00	0.00	571.00
M FRONT WING RH ASS	1.00	571.00	0.00	571.00
M FR STRENGTHEN LH ASS	1.00	257.00	0.00	257.00
M FR STRENGTHEN RH	1.00	184.00	0.00	184.00
M MUDGUARD LH ASS	1.00	194.00	0.00	194.00
M MUDGUARD RH ASS	1.00	159.00	0.00	159.00
M SUPPORT F/WING LH INF AV	1.00	171.00	0.00	171.00
M SUPPORT F/WING RH INF AV	1.00	172.00	0.00	172.00
M ACCOUSTIC SEAL LH	1.00	61.00	0.00	61.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
Soh Ching Chye		Cust No/Name /Soh Ching Chye	
9 Rivervale Crescent		Reg No/Reg Date SGZ3300U / 24/01/2017	
#12-29		Date In/Mileage 04/06/2021/ 0	
Singapore 545086		Chassis No VF73ABHZTGJ811723	
Contact No Mobile: 81611180		Engine No 10JBHD3064541	
		Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML	
		Colour/Trim EUM SABLE / IXF YATAGO GREY	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	04/06/2021/ 16:40	QUK	282 / Kevin Leong	16595

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M ACCOUSTIC SEAL RH	1.00	60.00	0.00	60.00
P ACCOUSTIC SEAL	2.00	47.00	0.00	94.00
M FRONT WING FIX	1.00	64.00	0.00	64.00
M ENGINE BONNET ASS	1.00	1042.00	0.00	1042.00
M BONNET HINGE LH	1.00	178.00	0.00	178.00
M BONNET HINGE RH	1.00	178.00	0.00	178.00
M SOUND PROOFING	1.00	235.00	0.00	235.00
M BONNET BUFFER	1.00	26.00	0.00	26.00
M RIVET NOIR	10.00	1.00	0.00	10.00
M RAILLING	1.00	191.00	0.00	191.00
M GRILLE SEAL	1.00	68.00	0.00	68.00
M SOUND PROOFING	1.00	624.00	0.00	624.00
M BUMPR DEFLECTOR	1.00	493.00	0.00	493.00
M FRONT LIGHT LH	1.00	521.00	0.00	521.00
M FRONT LIGHT RH	1.00	521.00	0.00	521.00
M HEADLIGHT ASSY LH	1.00	718.00	0.00	718.00
M HEADLIGHT ASSY RH	1.00	718.00	0.00	718.00
M HORN	1.00	88.00	0.00	88.00
M COVER	1.00	55.00	0.00	55.00
M LATCHES	2.00	3.00	0.00	6.00
M CONDENSER	1.00	796.00	0.00	796.00
M CONDENS BRACKET	1.00	58.00	0.00	58.00
M COND DEFLECTOR	1.00	72.00	0.00	72.00
M FREON TUBE	1.00	517.00	0.00	517.00
M FREON TUBE	1.00	222.00	0.00	222.00
M UNION SCREW 12/10X150-L37,25	1.00	17.00	0.00	17.00
M UNION SCREW DIAM 12/10X100-29	1.00	16.00	0.00	16.00

Confirm & accepted by

Parts	25,403.00
Labour	12,410.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	340.00
Total (w/o GST)	38,153.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.