



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 384L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	N/S CENTRE ALUMINIUM DOOR	BADLY DENTED	3,000.00	1,500.00
1	N/S CENTRE ALUMINIUM DOOR LOCK	DISLODGE	220.00	150.00
1	N/S CENTRE ALUMINIUM DOOR LOGO AND LETTERING	NECESSARY	600.00	300.00
			3,820.00	1,950.00
	LABOUR			
	REMOVE THE NECESSARY AFFECTED PARTS.STRAIGHTEN N/S CENTRE ALUMINIUM DOOR.LOWER FRAME AND RAIL AND REPLACE PARTS.		800.00	300.00
	REMOVE AND REFIX N/S CENTRE DOOR PARTS.		300.00	100.00
	SPRAYPAINT ON ALL AFFECTED PARTS.		1,000.00	300.00
			2,100.00	700.00
	GRAND TOTAL		5,920.00	2,650.00
	RECOMMENDED COST OF REPAIRS			2,650.00

Report Ref No. CS3/GAI21005136/R1tf3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.