

SJE 6932B.

Toyota Axio 1496CC

NZE416077749

TP III

Denise

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Front Number Plate

Front Number Plate Holder

Front Bumper

Front Bumper Clips

Front Bumper Side Holder x02

Front Bumper Reinforcement

Front Bumper Sponge

Front Bumper Fog Lamp Cover x02

Front Grille

Front Grille Clips

Front Grille Logo

Headlamp x02

2 x4
New

Deformed

New

New

2 x4
New

cracked

New

New

RH
cracked

30(SN) X

30(SN) X

481.50 -

30(SN) -

54.7 x 2 = 109.40 -

329.50 -

172.50 -

40.9 x 2 = 81.80 X

347.20 -

20(SN) -

38.50 -

781.9 x 2 = 1563.80

781.80

SIF 6932B.

Rear Number Plate	Cracked	30(SN) ✓
Rear Number Plate Holder		30(SN) ✓
Rear Bumper	Distorted	585.10 ✓
Rear Bumper Clips	Nec	30(SN) ✓
Rear Bumper Side Holder x 2	Damaged	41.9 x 2 = 83.80 ✓
Rear Bumper Impact Bracket x 2	Distorted	112.8 x 2 = 225.60 ✓ 112.80
Reverse Sensor	Damaged	280(SN) 200(SN) ✓
Rear End Panel	Distorted	595.50 ✓
Rear End Panel Top Garnish	Cracked	166.30 ✓
Rear End Panel Top Garnish Clips	Nec	20(SN) ✓
Rear End Panel Sealant	Nec	60(SN) ✓
Taillamp x 2	Cracked	321 x 2 = 642 ✓
Taillamp Panel x 2	Distorted	160.8 x 2 = 321.60 ✓
Taillamp Panel Lower Bracket x 2	Cracked	64.4 x 2 = 128.80 ✓
Bootlid	Distorted	849.30 ✓
Bootlid Lock	Damaged	185.20 ✓
Bootlid Lock Cover	Cracked	42.40 ✓
Bootlid Hinge x 2	Best	42.9 x 2 = 85.80 ✓
Bootlid Outer Garnish	Cracked	220.30 ✓
Bootlid Weatherstripe	At	172.50 ✓

SJE 032 B.

Boothid Inner Trim	torn	296.60	✓
Boothid Inner Trim Clips.	NEC	30(SN)	✓
Toyota Logo	} NEC	47.20	✓
Axio Wording.		44.20	✓
X Emblem.		34.40.	✓
Rees Fender x02	Distorted.	945 x 2 = 1890.	✓
Rees Fender Inner Panel x02	Rys	681.80	+
Rees Fender Wheel House RH.	Dented	559.50	✓
Rees Fender Inner Trim x02	crumpled	378.5 x 2 = 757	✓
Rees Fender Inner Trim Clips.	NEC	60(SN)	✓
Rees Fender Inner Shield x02	RH torn	89.5 x 2 = 179. 89.50	
Rees Fender Inner Shield Clips.	NEC	40(SN) 20(SN)	
Rees Fender Air Vent x02	RH could	58 x 2 = 116. 58.	
Rees Windscreen	Cut	1341.20	✓
Rees Windscreen Moulding.	} NEC	180.50	✓
Rees Windscreen Sealant.		60(SN)	✓
Rees RH Door	Rys	1165.20.	X
Rees RH Door Lock	NE NEC	395.60	X.

SJB 6932B.

Spare Tyre Panel	Buckled	965.20 /
Spare Tyre Panel Side x02	^{RA} Dist'd	^{205.20} $205.2 \times 2 = 410.40$
Spare Tyre Panel Top Cover	crumpled	515.90 /
Spare Tyre Panel Lock Screw	Dend	49.80 /
Spare Tyre Panel Side Tray x02	^{RA} Dist'd	$65 \times 2 = 130.65$
Rear Seat Backrest Board	crumpled	187.20 /
Rear Exhaust Pipe	Bent	655.90 /
Rear Exhaust Mounting	14 m	48 x
Rear Exhaust Gasket	air	30 (SN) /
Rear Exhaust Heat Shield.	crumpled	143.90 /
Centre Exhaust Pipe.	never	782 x
Rear Axle	2 HP New	2713.40. x
Rear Axle Bearing x02		$220.1 \times 2 = 440.20$ x
Rear Shock Absorber x02		$235 \times 2 = 470.$ x

14539.70

10904.77

S.N: 620

SJE 6932B.

Panel Beating (Front)	600 300	
Spray Painting (Front)	600 200	
Wiring (Front).	50 30	
Panel Beating (Rear)	3200 2000.	
Spray Painting (Rear)	2400 1600	
Wiring (Rear)	100 30	
To remove reverse sensor	100 50	
To remove upholstery and rear seat	350 200	
To remove rear windscreen.	180 120	
To transfer bootlid fittings.	150 60	
To remove rear and centre exhaust pipe.	300 80	
To transfer door fittings.	150 X	
To remove rear undercarriage.	380 280.	
To perform wheel alignment.	150 80	5150
Towing Fees. (King Roller)	150 120.	
	total: 16674.77	
	n/s: 13.3K.	
	18 Days.	