11/17/21, 12:54 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21006540/AGS3Q2

17/11/2021 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070012930 **Claimant Vehicle** SLT3953H Insured Vehicle No: SDM8877T

No:

Date of Loss: 03/06/2021 Nature of Claim: TP Claim No: 4186090638SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT3953H**

Make & Model: OPEL MOKKA, 1.6 (A) A2163245GU7X0107 Engine No: Reg. Date: 27/10/2017 (Man. Year: 2017) Chassis No: W0LJD7EC7HB140470

Colour: Odometer: 191534 km White

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 215/55 R18 Rear Tyre Size: 215/55 R18 Front Left Side: Rear Left Side: Comforser 6 mm Comforser 6 mm Front Right Side: Comforser 6 mm Rear Right Side: Comforser 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------|----------------------|------------|------------|--------|
| Parts | | 11,471.60 | 4,253.40 | 7,218.20 | 62.92 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 5,710.00 | 1,280.00 | 4,430.00 | 77.58 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Gross Total (S\$) | 17,181.60 | 5,533.40 | 11,648.20 | 67.79 |
| | + GST 7.00/7.00% (S\$) | 1,202.71 | 387.34 | 815.37 | 67.79 |
| | Nett Amount (S\$) | 18,384.31 | 5,920.74 | 12,463.57 | 67.79 |
| | + Loss of Use (3.0 x | S\$50.00/day) (S\$) | 150.00 | | |
| | + Do | c/Search Fee (S\$) | 2.00 | | |
| | | Nett Liability (S\$) | 6,072.74 | | |

INSPECTION

Date of Assignment: 08/06/2021

Date Inspected: 08/06/2021 Inspected At: 23 Kaki Bukit Ave 4, #04-01

Global Sum Settlement (S\$)

1st Autoworks Pte Ltd (HQ)

6.000.00

Singapore 415933

Estimated Period of Repair: 3.0 days

Adjuster: **ADRIAN LING** Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|--------|-------------|---|---------------------------------------|---------------------------|------------------------|
| 1 | 1 | | *REAR TAILGATE | Not Necessary | 1,840.00 FL | *- FL |
| 2 | 1 | | *REAR TAILGATE OPEL LOGO | Not Necessary | 199.00 FL | *- FL |
| 3 | 1 | | *LETTERING MOKKA | Not Necessary | 146.00 FL | *- FL |
| 1 | 1 | | *LETTERING CDTI | Not Necessary | 110.00 FL | *- Fl |
| 5 | 1 | | *REAR WINDSCREEN WITH MOULDING | Not Necessary | 1,258.00 FL | *- FL |
| 3 | 1 | | *LHR TAILLAMP | Not Necessary | 564.00 FL | *- FL |
| 7 | 1 | | *RHR TAILLAMP | Not Necessary | 564.00 FL | *- FL |
| 3 | 1 | | *REAR BUMPER UPPER | Deformed | 1,487.00 FL | *1,487.00 FL |
| 9 | 1 | | *REAR BUMPER LOWER | Deformed | 990.00 FL | *990.00 FL |
| 10 | 1 | | *REAR BUMPER TOWING COVER | Not Necessary | 90.00 FL | *- FL |
| 11 | 1 | | *REAR BUMPER SILL PLATE | Deformed | 344.00 FL | *344.00 FL |
| 12 | 1 | | *LHF BUMPER REFLECTOR | Cracked | 150.00 FL | *150.00 FL |
| 13 | 1 | | *RHF BUMPER REFLECTOR | Not Necessary | 150.00 FL | *- FL |
| 14 | 1 | | *LHR FENDER PROTECTOR | Not Necessary | 190.00 FL | *- FL |
| 15 | 1 | | *RHR FENDER PROTECTOR | Not Necessary | 190.00 FL | *- FL |
| 16 | 1 | | *LHR BUMPER BRAKET ,GUIDE | Cracked | 70.00 FL | *70.00 FL |
| 17 | 1 | | *RHR BUMPER BRAKET ,GUIDE | Cracked | 70.00 FL | *70.00 FL |
| 18 | 1 | | *LHR BUMPER BRACKET | Damaged | 65.00 FL | *65.00 FL |
| 19 | 1 | | *RHR BUMPER BRACKET | Damaged | 65.00 FL | *65.00 FL |
| 20 | 1 | | *REAR BUMPER CENTRE BRACKET | Not Necessary | 85.00 FL | *- FL |
| 21 | 1 | | *REAR BUMPER ABSORBER -RH | Damaged | 82.00 FL | *82.00 FL |
| 22 | 1 | | *REAR BUMPER ABSORBER -LH | Damaged | 82.00 FL | *82.00 FL |
| 23 | 1 | | *REAR BUMPER REINFORCEMENT BAR | Dented | 671.00 FL | *671.00 FL |
| 24 | 1 | | *REAR END PANEL | Not Necessary | 1,241.00 FL | *- FL |
| 25 | 1 | | *REAR END PANEL TRIM | Not Necessary | 164.00 FL | *- FL |
| 26 | 1 | | *SET REVERSE SEBNSOR WITH REVERSE SENSOR SEAL | Damaged | 660.00 FL | *160.00 FL |
| 27 | 1 | | *REVERSE SENSOR WIRING HARNESS | Cracked | 450.00 FL | *450.00 FL |
| 28 | 10 | | *SET REAR BUMPER UPPER CLIP | Necessary | 65.00 FL | *20.00 FL |
| 29 | 10 | | *SET REAR BUMPER LOWER CLIP | Necessary | 65.00 FL | *20.00 FL |
| 30 | 8 | | *SET REAR END PANEL TRIM CLIP | Not Necessary | 52.00 FL | *- FL |
| 31 | 1 | | *SET TAIL GATE INNER TRIM BOARD CLIP | Not Necessary | 65.00 FL | *- FL |
| 32 | 1 | | *REAR END PANEL INSULATION SEAL | Not Necessary | 120.00 FS | *- FS |
| 33 | 1 | | *TAILGATE WINDSCREEN SEALANT | Not Necessary | 120.00 FS | *- FS |
| 34 | 1 | | *TAILGATE WINDSCREEN SOLAR FILM | Not Necessary | 180.00 FS | *- FS |
| 35 | 1 | | *DIESEL STICKER | Not Necessary | 30.00 FS | *- FS |
| 36 | 1 | | *PTE HIRE STICKER | Not Necessary | 20.00 FS | *- FS |
| | nchise | part. S=Spc | Nett. L=ListItemDisc. | , | | |
| | | · | - List Item Discount on L Items | Sub Total (S\$) 10.00/10.00% (S\$) | 12,694.00 1,222.40 | 4,726.00 472.60 |
| | | | | Total Parts (S\$) | 11,471.60 | 4,253.40 |
| | | | Report was unsubmitted during this print- | out. | , | |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------|--|------------|------------|--------|
| Labe | our Items | | | |
| 1 | TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS | New | 2,600.00 | 650.00 |
| 2 | CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA | New | 2,200.00 | 550.00 |
| 3 | TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT | New | 130.00 | 0.00 |
| 4 | TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR | New | 65.00 | 30.00 |
| 5 | TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST | New | 130.00 | 0.00 |
| 6 | TO REMOVE AND REFIX REVERSE SENSOR AND CONDCUT TEST | New | 130.00 | 50.00 |
| 7 | TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE | New | 260.00 | 0.00 |
| 8 | TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE | New | 65.00 | 0.00 |
| 9 | TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN | New | 130.00 | 0.00 |
| | Gross Labour | 5,710.00 | 1,280.00 | |
| | Report was unsubmitted during this | print-out. | | |

< END OF ESTIMATES >