



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCX 3457J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DISTORTED	1,428.00	850.00
2	REAR BUMPER BEAM BRACKET @\$135.00	BENT	270.00	270.00
1	REAR BUMPER BEAM	BENT	296.00	296.00
2	REAR BUMPER SIDE RETAINER @\$58.00	NECESSARY	116.00	116.00
2	REAR NUMBER PLATE LAMP @\$59.00	NOT NECESSARY	118.00	-
2	TAIL LAMP @\$598.00	CRACKED	1,196.00	760.00
2	TAIL LAMP LOWER PANEL @\$196.00	N/S DENTED	392.00	196.00
2	TAIL LAMP PANEL @\$289.00	TO REPAIR SEE LABOUR	578.00	-
2	REAR FENDER INNER COWLING @\$176.00	NOT NECESSARY	352.00	-
1	BOOT LID	DENTED	945.00	810.00
2	BOOT LID LAMP @\$260.00	CRACKED	520.00	520.00
1	BOOT LID LOGO	NECESSARY	55.00	55.00
1	BOOT LID EMBLEM "LANCER"	NECESSARY	69.00	69.00
1	BOOT LID EMBLEM "MITSUBISHI"	NECESSARY	65.00	65.00
1	BOOT LID EMBLEM "GLXI"	NECESSARY	62.00	62.00
2	BOOT LID HINGE @\$125.00	NOT NECESSARY	250.00	-
1	BOOT LID TOP LOCK	DAMAGED	189.00	189.00
1	BOOT LID LOWER LOCK	NOT NECESSARY	21.00	-
1	BOOT LID WEATHER STRIP	CUT	160.00	160.00
1	REAR END PANEL	DISTORTED	629.00	629.00
1	REAR END PANEL TOP GARNISH	DEFORMED	144.00	144.00
1	REAR END PANEL INNER TRIM	DEFORMED	285.00	285.00
1	REAR FLOOR PANEL	BUCKLED	1,460.00	955.00
1	REAR FLOOR PANEL TOP BOARD	TORN	189.00	189.00
1	REAR FLOOR TOWING HOOK PANEL	TO REPAIR SEE LABOUR	450.00	-
1	REAR CHASSIS MEMBER LH	TO REPAIR SEE LABOUR	924.00	-
1	CENTER EXHAUST	NOT NECESSARY	1,260.00	-
1	CENTER EXHAUST INSULATOR	NOT NECESSARY	195.00	-
1	SET CENTER EXHAUST GASKET	NOT NECESSARY	60.00	-

Report Ref No. CS/AGI21006542/Aqf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST PIPE	BENT	959.00	685.00
2	REAR EXHAUST MOUNTING @\$56.00	NOT NECESSARY	112.00	-
1	REAR EXHAUST INSULATOR	NOT NECESSARY	185.00	-
1	REAR EXHAUST GASKET	NECESSARY	60.00	30.00
	LESS 10% DISCOUNT		-1,399.40	-733.50
			12,594.60	6,601.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	80.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	SET TAIL LAMP CLIP (SN)	NECESSARY	60.00	20.00
2	TAIL LAMP LOWER PANEL SEALANT @\$80.00 (SN)	NOT NECESSARY	160.00	-
1	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	80.00	-
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	60.00	10.00
1	SET REAR END PANEL INNER TRIM CLIP (SN)	NECESSARY	80.00	20.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	150.00	60.00
1	REAR FLOOR PANEL SEALANT (SN)	NECESSARY	150.00	60.00
1	REAR FLOOR TOWING HOOK PANEL SEALANT (SN)	NOT NECESSARY	150.00	-
1	REAR EXHAUST CHROME PIPE (SPECIAL TYPE)(SN)	CUT	350.00	100.00
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			1,700.00	500.00
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT,WELD,CUT,GRAZE,KNOCK STRAIGHTEN,ADJUST AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF TAIL LAMP PANEL,REAR FLOOR TOWING HOOK PANEL AND REAR CHASSIS MEMBER LH.		1,800.00	1,200.00
	TO PUTTY,SPRAY PAINT POLISH,WAX.		1,800.00	1,000.00
	TO SPRAY TUFF COAT.		250.00	80.00
	WIRING,BULB CHECKING.		120.00	30.00
	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR.		350.00	80.00
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	80.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00

Report Ref No. CS/AGI21006542/Aqf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSFER BOOTLID MECHANISM.	NOT NECESSARY	80.00	60.00
	REMOVE AND REFIX REAR EXHAUST PIPE.		180.00	80.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.		180.00	-
			4,920.00	2,580.00
<b>GRAND TOTAL</b>			<b>19,214.60</b>	<b>9,681.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>7,700.00</b>

Report Ref No. CS/AGI21006542/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.