

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21006544/KQF3E2

Date: 29/07/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28653857MKC
Claimant Vehicle No :	GBK9135D	Insured Vehicle No :	YN3626E
Date of Loss:	04/06/2021	Nature of Claim:	TP
		Claim No:	636437

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK9135D	Engine No:	1KDB064725
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y50K216031
Reg. Date:	15/01/2021 (Man. Year: 2020)	Odometer:	1689 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9/9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,926.97	2,436.95	490.02	16.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,290.00	940.00	350.00	27.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,216.97	3,376.95	840.02	19.92
+ GST 7.00/7.00% (S\$)	295.19	236.39	58.80	19.92
Nett Amount (S\$)	4,512.16	3,613.34	898.82	19.92

INSPECTION

Date of Assignment:	09/06/2021	
Date Inspected:	18/06/2021	Inspected At: Cheng Hoe Motor Service (HQ) BLK 1019, YISHUN IND. PARK A, #01-374 Singapore 768761
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Jul 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK9135D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Bent	1,794.20 FL	*1,650.40 FL
2	1		*FRONT LH DOOR TOP HINGE	Repair	110.00 FL	*- FL
3	1		*FRONT LH CORNAL GARNISH	Serviceable	336.30 FL	*- FL
4	1		*HEADLAMP LH	Cut	928.70 FL	*892.10 FL
5	1		*FRONT LH SIDE MIRROR	Dented / Cut	600.10 FL	*600.10 FL
6	1		*FRONT LH DOOR COY STICKER	Necessary	20.00 FS	*20.00 FS
7	1		*FRONT LH DOOR ADVERTISEMENT STICKER	Necessary	80.00 FS	*60.00 FS
					Sub Total (\$\$)	3,869.30
					- List Item Discount on L Items 25.00/25.00% (\$\$)	942.33
					Total Parts (\$\$)	2,926.97
						2,436.95

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT LH DOOR TRANSFER DOOR LOCK ASSY, INNER TRIM BOARD, RUBBER, REMOVE & REFIX FRT LH SIDE MIRROR & CORNAL GARNISH, KNOCK & REPAIR FRT LH W/SCREEN PILLAR & REALIGN CABIN POSITION	New	700.00	400.00
2	REMOVE & REFIX FRT LH DOOR GLASS	New	60.00	60.00
3	PUTTY & RESPRAY ON FRT LH CORNAL GARNISH, FRT LH DOOR, PILLAR	New	500.00	450.00
4	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,290.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >