

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006547/APA3Q2
Date: 18/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100425546
Claimant Vehicle No :	SKM6650K	Insured Vehicle No :	SKU8608D
Date of Loss:	03/06/2021	Nature of Claim:	TP
		Claim No:	7489501872SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM6650K	Engine No:	2AR1012801
Make & Model:	LEXUS ES300H, 2.5 (A)	Chassis No:	JTHBW1GG602049951
Reg. Date:	23/12/2013 (Man. Year: 2013)	Odometer:	92454 km
Colour:	Black		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,359.04	1,146.24	2,212.80	65.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	860.00	1,420.00	62.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,639.04	2,006.24	3,632.80	64.42
Approved Total (Overridden) (S\$)		1,600.00		

Nett Amount (S\$)	5,639.04	1,600.00	4,039.04	71.63
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 04/06/2021

Date Inspected: 04/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Unimotor Company - Kaki Bukit (HQ)
1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT)
Singapore 417883

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Torn	1,021.60 FL	*1,021.60 FL
2	1		*REAR BUMPER R/H SIDE RETAINER	Cracked	197.00 FL	*197.00 FL
3	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
4	1		*REAR FENDER ASSY (RIGHT)	Repair	1,352.80 FL	*- FL
5	1		*REAR FENDER R/H INNER BRACKET	Not Necessary	187.60 FL	*- FL
6	1		*REAR FENDER INNER SHIELD	Not Necessary	211.60 FL	*- FL
7	8		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FL	*- FL
8	1		*REAR R/H SPORT WHEEL	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,665.60	1,273.60
- List Item Discount on L Items 10.00/10.00% (\$)	306.56	127.36
Total Parts (\$)	3,359.04	1,146.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE FRONT /REAR DAMAGED	New	80.00	30.00
2	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	New	800.00	300.00
3	TO PUTTY AND RESPRAY DAMAGED PORTION	New	800.00	500.00
4	TO SEND VEHICLE COR COMPUTER ALIGHTMENT	New	120.00	0.00
5	TO SPRAY UNDERCOATING IN REPAIR	New	80.00	30.00
6	TO DISM/REFIX REAR SEAT ,TRAY ASSY PILLER LINING ROOF LINING	New	280.00	0.00
7	TO RESET ECU AFTER REPAIR	New	120.00	0.00
Gross Labour Cost (S\$)			2,280.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >