



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

TP A16
Xiao Teng

LKK

DATE: 05/06/2021 OUR REF: UAPL1461
REPAIR ESTIMATE TO THE VEHICLE LEXUS ES300 NO: SKM6650K

1 REAR BUMPER ASSY	torn	\$	1,021.60	✓
1 REAR BUMPER R/H SIDE RETAINER	cracked	\$	197.00	✓
10 REAR BUMPER CLIPS	new	\$	55.00	✓
1 REAR FENDER ASSY (RIGHT)	new	\$	1,352.80	X
1 REAR FENDER R/H INNER BRACKET	new	\$	187.60	X
1 REAR FENDER INNER SHIELD	new	\$	211.60	X
8 REAR FENDER INNER SHIELD CLIPS	new	\$	40.00	X
		\$	3,065.60	
		\$	766.40	
		\$	2,299.20	

LESS: 10%.....

SPECIAL NETT:-

1 REAR R/H SPORT WHEEL

\$ 600.00 X

LABOUR CHARGES:-

TO DISM/REWIRE FRONT/REAR DAMAGED

\$ 80.00 30

TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS

\$ 800.00 300

TO PUTTY AND RESPRAY DAMAGED PORTION

\$ 800.00 \$w

TO SEND VEHICLE COR COMPUTER ALIGHTMENT

860 \$ 120.00 X

TO SPRAY UNDERCOATING IN REPAIR

\$ 80.00 30

TO DISM/REFIX REAR SEAT, TRAY ASSY, PILLER LINING, ROOF LINING

\$ 280.00 X

TO RESET ECU AFTER REPAIR

\$ 120.00 X

\$ 5,179.20

total 2006.24

L/S: 1.6K

03 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1.6K