

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21006555/T1RA3Q2
Date: 15/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900152172
Claimant Vehicle No :	SHB1051R	Insured Vehicle No :	SKE2920A
Date of Loss:	05/06/2021	Nature of Claim:	TP
		Claim No:	3439160651SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB1051R		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2F16892
Reg. Date:	17/12/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FU303088877
Colour:	Maroon	Odometer:	153487 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,088.54	879.00	6,209.54	87.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,601.00	1,270.00	1,331.00	51.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,689.54	2,149.00	7,540.54	77.82
	+ Loss of Use (4.0 x S\$50.00/day) (S\$)	200.00		
	+ Car Rental (4.0 x S\$117.17/day) (S\$)	468.68		

+ Doc/Search Fee (S\$)	7.00
Nett Liability (S\$)	2,824.68

INSPECTION

Date of Assignment: 08/06/2021

Date Inspected: 08/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Strides Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PAD ,FR WHEEL LH (DISC 25%)	Necessary	59.60 F	*44.70 F
2	1		*EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	Necessary	54.60 F	*40.95 F
3	1		*FENDER SUB-ASSY ,FR ,LH (DISC 25%)	Bent	977.80 F	*733.35 F
4	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
5	1		*SOLAR FILM	Not Necessary	125.00 F	*- F
6	1		*WEATHERSTRIP ,FRONT DOOR FIX WINDOW LH	Not Necessary	76.40 F	*- F
7	1		*GLASS ,FRONT DOOR FIX WINDOW LH	Not Necessary	69.90 F	*- F
8	1		*COVER SUB-ASSY ,FRONT PILLAR ,UPR LH	Not Necessary	96.90 F	*- F
9	1		*MIRROR ASSY ,OUTER REAR VIEW ,LH	Not Necessary	1,339.30 F	*- F
10	1		*TYRE	Not Necessary	126.74 F	*- F
11	1		*LINER FR FENDER LH	Not Necessary	210.30 F	*- F
12	1		*SUPPORT ,FR BUMPER LH	Not Necessary	82.30 F	*- F
13	1		*COVER ,FR BUMPER	Repair	521.00 F	*- F
14	1		*PANEL SUB-ASSU ,FRONT DOOR LH	Repair	1,300.70 F	*- F
15	1		*COVER ,OUTER MIRROR LH	Repair	108.60 F	*- F
16	1		*WHEEL ,DISC FRONT	Repair	1,879.40 F	*- F

F=Franchise part.

Total Parts (S\$)
7,088.54
879.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	507.00	300.00
2	SPRAY PAINT	New	1,494.00	800.00
3	TO REMOVE AND REFIX WING MIRROR	New	120.00	60.00
4	TO TRANSFER DOOR MECHANISM	New	120.00	0.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	80.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
7	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
8	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			2,601.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >