

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006557/KVF3N2**Date:** 14/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00099342000

**Claimant Vehicle
No :** SMW7030S**Insured
Vehicle No :** SLX55Z

Date of Loss: 09/06/2021

Nature of Claim: TP

Claim
No: SNM21D203272/C02/TANKW**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMW7030S**

Make & Model: HONDA SHUTTLE, 1.5 G (A)

Engine No: L15B6022249

Reg. Date: 02/12/2020 (Man. Year: 2019)

Chassis No: GK82101909

Colour: Metallic Red

Odometer: 5116 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,669.00	3,669.00	0.00	0.00
Miscellaneous Items	235.00	235.00	0.00	0.00
Labour	2,220.00	1,990.00	230.00	10.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,124.00	5,894.00	230.00	3.76
+ GST 7.00/7.00% (S\$)	428.68	412.58	16.10	3.76
Nett Amount (S\$)	6,552.68	6,306.58	246.10	3.76

INSPECTION

Date of Assignment:	11/06/2021	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun) 10 ANG MO KIO IND PARK 2A #01-04 ANG MO KIO AUTOPOINT . SINGAPORE 568047 REPAIRER: CHENG HOE MOTOR SERVICE
Date Inspected:	10/06/2021	Inspected At:	
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Oct 2021)	
Parts:	N/A	HONDA SHUTTLE 1.5 G (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW7030S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc front bumper	Bent	540.00 F	*540.00 F
2	1		*1 pc front bumper reinforcement	Bent	260.00 F	*260.00 F
3	1		*1 pc front bumper lower centre grille	Distorted	90.00 F	*90.00 F
4	1		*1 pc front bumper LH side fog lamp garnish	Missing	60.00 F	*60.00 F
5	1		*2 pcs front bumper side retainers @ \$9/pc	Cracked	18.00 F	*18.00 F
6	1		*6 pcs front bumper side retainers @ \$2/pc	Cracked	12.00 F	*12.00 F
7	1		*1 pc front grille housing	Mtg Cracked	170.00 F	*170.00 F
8	1		*1 pc front grille housing outer garnish	Cut	250.00 F	*250.00 F
9	1		*1 pc front grille logo (black)	Cut	255.00 F	*255.00 F
10	1		*1 pc front grille lower chrome	Dented	100.00 F	*100.00 F
11	1		*2 pcs headlamps @ \$510/pc	O/s Mtg Cracked/N/s Broken	1,020.00 F	*1,020.00 F
12	1		*2 pcs headlamp lower brackets @ \$36/pc	Cracked	72.00 F	*72.00 F
13	1		*1 pc front support panel	Bent	390.00 F	*390.00 F
14	1		*1 pc front LH fender	Bent	150.00 F	*150.00 F
15	1		*1 pc front LH fender inner shield	Cracked	85.00 F	*85.00 F
16	1		*6 pcs front LH fender inner shield clips @ \$2/pc	Necessary	12.00 F	*12.00 F
17	1		*1 pc front LH fender extension arm	Bent	95.00 F	*95.00 F
18	1		*1 pc front LH fender gusset plate	Distorted	40.00 F	*40.00 F
19	1		*1 pc front LH fender gusset	Bent	50.00 F	*50.00 F

F=Franchise part.

Total Parts (\$\$) **3,669.00** **3,669.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 pc front LH rim (Dented)	200.00	200.00
2	1	1 unit coolant (Necessary)	35.00	35.00
Sub Total (\$\$)			235.00	235.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Towing	New	50.00	50.00
2	Remove & refix air-con condenser,vacuum & refill gas	New	100.00	100.00
3	Remove & refix front bumper & attachments,grille,front LH fender;to cut,weld & renew frt LH fender extension arm,frt support panel;knocking & repair front LH chassis frame & realign the same	New	900.00	800.00
4	Putty & respray front bumper,bonnet,both fenders,frt support panel,frt LH door & all affected areas	New	1,000.00	900.00
5	Remove & refix frt LH rim,tyre,balance & realign the same	New	50.00	20.00
6	To conduct computer wheel alignment	New	60.00	60.00
7	Rustproofing	New	60.00	60.00
Gross Labour Cost (\$\$)			2,220.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >