

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 10 Jun 2021)
Parts: N/A HONDA SHUTTLE 1.5 G (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMW7030S)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc front bumper	Bj	0.00	*540.00 F ✓
2	1		*1 pc front bumper reinforcement	Bj	0.00	*260.00 F ✓
3	1		*1 pc front bumper lower centre grille	D/L	0.00	*90.00 F ✓
4	1		*1 pc front bumper LH side fog lamp garnish	M/L	0.00	*60.00 F ✓
5	1		*2 pcs front bumper side retainers @ \$9/pc	C/M	0.00	*18.00 F ✓
6	1		*6 pcs front bumper side retainers @ \$2/pc	C/M	0.00	*12.00 F ✓
7	1		*1 pc front grille housing	M/C/M	0.00	*170.00 F ✓
8	1		*1 pc front grille housing outer garnish	C/L	0.00	*250.00 F ✓
9	1		*1 pc front grille logo (black)	C/L	0.00	*255.00 F ✓
10	1		*1 pc front grille lower chrome	D/L	0.00	*100.00 F ✓
11	1		*2 pcs headlamps @ \$510/pc		0.00	*1,020.00 F ✓
12	1		*2 pcs headlamp lower brackets @ \$36/pc	C/M	0.00	*72.00 F ✓
13	1		*1 pc front support panel		0.00	*390.00 F ✓
14	1		*1 pc front LH fender	Bj	0.00	*150.00 F ✓
15	1		*1 pc front LH fender inner shield	C/M	0.00	*85.00 F ✓
16	1		*6 pcs front LH fender inner shield clips @ \$2/pc	M/L	0.00	*12.00 F ✓
17	1		*1 pc front LH fender extension arm	Bj	0.00	*95.00 F ✓
18	1		*1 pc front LH fender gusset plate	D/L	0.00	*40.00 F ✓
19	1		*1 pc front LH fender gusset	Bj	0.00	*50.00 F ✓
Total Parts (\$\$)						3,669.00

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 pc front LH rim	200.00 ✓
2	1	1 unit coolant	35.00 ✓
Sub Total (\$\$)			235.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
	<u>Labour Items</u>		
	Towing	New	50.00 ✓

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Particulars	Lab.Type	Amount
2 Remove & refix air-con condenser,vacuum & refill gas	New	✓ 100.00
3 Remove & refix front bumper & attachments,grille,front LH fender;to cut,weld & renew frt LH fender extension arm,frt support panel;knocking & repair front LH chassis frame & realign the same	New	800. 900.00
4 Putty & respray front bumper,bonnet,both fenders,frt support panel,frt LH door & all affected areas	New	900 1,000.00
Remove & refix frt LH rim,tyre,balance & realign the same	New	200 50.00
To conduct computer wheel alignment	New	✓ 60.00
Rustproofing	New	✓ 60.00
Gross Labour Cost (S\$)		2,220.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >