

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006559/KPA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700074981
Claimant Vehicle No :	SLQ2896L	Insured Vehicle No :	SLT6973E
Date of Loss:	06/06/2021	Nature of Claim:	TP
		Claim No:	1047481011SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ2896L	Engine No:	3A92UGB6463
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH006392
Reg. Date:	03/07/2017 (Man. Year: 2017)	Odometer:	72278 km
Colour:	Metallic Silver		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 2 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,437.00	4,931.40	7,505.60	60.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,685.00	4,320.00	1,365.00	24.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,122.00	9,251.40	8,870.60	48.95
Approved Total (Overridden) (S\$)		7,400.00		
(S\$)	18,122.00	7,400.00	10,722.00	59.17
+ GST 7.00/7.00% (S\$)	1,268.54	518.00	750.54	59.17
Nett Amount (S\$)	19,390.54	7,918.00	11,472.54	59.17
+ Loss of Use (19.0 x S\$50.00/day) (S\$)		950.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,870.00		
Global Sum Settlement (S\$)		8,870.00		

INSPECTION

Date of Assignment:	09/06/2021	
Date Inspected:	09/06/2021 Inspected At:	City Auto Pte Ltd (Sin Ming) (HQ) Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est Singapore 575643
Estimated Period of Repair:	18.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Missing	708.00 FN	*708.00 FN
2	2		*REAR BUMPER RETAINER	Cracked	44.00 FN	*44.00 FN
3	10		*REAR BUMPER CLIPS	Necessary	50.00 FN	*50.00 FN
4	1		*REAR BUMPER SHIELD	O/S Missing	76.00 FN	*38.00 FN
5	2		*REAR BUMPER REFLECTOR	Missing	40.00 FN	*40.00 FN
6	1		*REAR RH FENDER	Bent	715.00 FN	*715.00 FN
7	1		*REAR RH FENDER INNER TRIM	Deformed	158.00 FN	*158.00 FN
8	1		*RH TAILLAMP	Broken	276.00 FN	*276.00 FN
9	1		*RH TAILLAMP PANEL	Bent	89.00 FN	*89.00 FN
10	1		*RH TAILLAMP CLIP HOLDER	Necessary	5.00 FN	*5.00 FN
11	1		*REAR END PANEL	Bent	402.00 FN	*402.00 FN
12	1		*REAR END PANEL TOP GARNISH	Serviceable	64.00 FN	*- FN
13	1		*REAR FLOOR PANEL	Bent	906.00 FN	*906.00 FN
14	1		*REAR EXHAUST MUFFLER	Serviceable	571.00 FN	*- FN
15	1		*REAR RH RIM	Serviceable	710.00 FN	*- FN
16	1		*REAR RH WHEEL BEARING	Not Necessary	114.00 FN	*- FN
17	1		*REAR RH SHOCK ABSORBER	Serviceable	204.00 FN	*- FN
18	1		*REAR AXLE BEAM	Serviceable	959.00 FN	*- FN
19	1		*REAR RH DOOR LOCK	Repair	290.00 FN	*- FN
20	1		*FRONT BUMPER	Bent	666.00 FN	*666.00 FN
21	1		*FRONT BUMPER TOW COVER	Dented	36.00 FN	*36.00 FN
22	1		*FRONT BUMPER LOWER GRILLE	Distorted	156.00 FN	*156.00 FN
23	10		*FRONT BUMPER CLIP	Necessary	50.00 FN	*50.00 FN
24	1		*FRONT BUMPER TOW COVER	Repeated	36.00 FN	*- FN
25	2		*FRONT BUMPER RETAINER	Serviceable	44.00 FN	*- FN
26	1		*FRONT BUMPER REINFORCEMENT	Bent	139.00 FN	*139.00 FN
27	1		*FRONT GRILLE	Serviceable	525.00 FN	*- FN
28	1		*FRONT GRILLE LOGO	Serviceable	42.00 FN	*- FN
29	1		*RH FOG LAMP	Serviceable	274.00 FN	*- FN
30	1		*RH FOG LAMP COVER	Serviceable	120.00 FN	*- FN
31	1		*HEADLAMP	O/S Mtg Cracked	1,088.00 FN	*544.00 FN
32	1		*FRONT SUPPORT PANEL	Repair	1,058.00 FN	*- FN
33	1		*AIR CON CONDENSER	Serviceable	683.00 FN	*- FN
34	1		*AIR CON DISCHARGE PIPE	Serviceable	190.00 FN	*- FN
35	1		*AIR CON LIQUID PIPE	Serviceable	275.00 FN	*- FN
36	1		*RADIATOR	Serviceable	872.00 FN	*- FN
37	1		*FAN COWLING	Serviceable	117.00 FN	*- FN
38	1		*FAN MOTOR	Serviceable	374.00 FN	*- FN
39	1		*FAN BLADE	Serviceable	70.00 FN	*- FN
40	1		*RADIATOR UPPER AIR GUIDE	Cracked	106.00 FN	*106.00 FN
41	1		*RADIATOR LOWER AIR GUIDE -LH	Cracked	18.00 FN	*18.00 FN
42	1		*RADIATOR LOWER AIR GUIDE -RH	Serviceable	18.00 FN	*- FN
43	1		*REAR KEYLESS ENTRY BUZZER	Serviceable	92.00 FN	*- FN
44	1		*REVERSE SENSOR	Missing	250.00 FS	*200.00 FS
45	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
46	1		*INSULATOR PASTE	Necessary	40.00 FS	*40.00 FS
47	1		*OFF-PEAK VEHICLE LICENSE PLATE SEAL	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	13,780.00	5,446.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	1,343.00	514.60
Total Parts (\$\$)	12,437.00	4,931.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR TRIMS ,SEATS AND UPHOLSTERY	New	120.00	100.00
2	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
3	TO SUPPLY PANEL SEALANT AND TO SEAL OFF ALL WELD SPOT SEAMS AND GAPS	New	90.00	90.00
4	TO SPRAY RUBBERIZED UNDER COATING	New	120.00	60.00
5	TO REMOVE AND INSTALL REAR SUSPENSION UNIT	New	200.00	0.00
6	TO CONDUCT WHEEL ALIGNMENT	New	75.00	60.00
7	TO REMOVE AND REFIT AIR CON COMPONENTS AND RECHARGE AIR CON GAS	New	100.00	0.00
8	TO INSTALL REVERSE SENSOR	New	40.00	40.00
9	TO CHECK WIRING AND LIGHTING	New	60.00	40.00
10	TO PULL AND REALIGN REAR CHASSIS MEMBER	New	250.00	250.00
11	TO REMOVE AND REFIT REAR EXHAUST MUFFLER	New	80.00	60.00
12	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN REFIX AND TO RENEW ACCIDENT PARTS	New	2,400.00	2,100.00
13	SPRAY PAINTING ON AFFECTED PARTS	New	2,000.00	1,400.00
			Gross Labour Cost (\$\$)	5,685.00
				4,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >