

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006560/R1QF3N2**Date:** 03/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00049562100

Claimant Vehicle No : SKX6175H **Insured Vehicle No :** GBJ4414L

Date of Loss: 07/06/2021 Nature of Claim: TP Claim No: SNM21D203271/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX6175H**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) Engine No: 1ZRY236828

Reg. Date: 21/12/2015 (Man. Year: 2015) Chassis No: MR053REH104542642

Colour: Grey Odometer: 97471 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,473.39	4,896.94	1,576.45	24.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,310.00	530.00	28.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,313.39	6,206.94	2,106.45	25.34
+ GST 7.00/7.00% (S\$)	581.94	434.49	147.45	25.34
Nett Amount (S\$)	8,895.33	6,641.43	2,253.90	25.34

INSPECTION

Date of Assignment: 11/06/2021

Date Inspected: 10/06/2021 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Blk 3 Pioneer Road North, #01-18
Singapore 628457

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Dec 2021)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX6175H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Torn	511.20 FL	*511.20 FL
2	1		*FRT BUMPER SIDE RETAINER	O/s Scratched	342.90 FL	*171.45 FL
3	1		*FRT BUMPER LOWER GRILLE	Not Necessary	182.10 FL	*- FL
4	1		*FRT BUMPER SPONGE	Cracked	191.60 FL	*191.60 FL
5	1		*FRT GRILLE	Missing	571.25 FL	*571.25 FL
6	1		*FRT GRILLE EMBLEM	Necessary	121.35 FL	*121.35 FL
7	2		*FRT HEADLAMP	Cracked	5,999.60 FL	*4,542.00 FL
8	2		*FRT HEADLAMP CHROME TRIM	Scratched	343.60 FL	*343.60 FL
9	1		*FRT BRACE PANEL	Repair	182.25 FL	*- FL
10	10		*FRT BUMPER CLIPS	Necessary	40.00 FS	*36.00 FS
11	6		*FRT GRILLE CLIP	Necessary	24.00 FS	*21.60 FS
12	10		*FRT BONNET INSULATOR CLIPS	Not Necessary	40.00 FS	*- FS
13	1		*FRT NUMBER PLATE	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,584.85	6,510.05
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,111.46	1,613.11
Total Parts (\$\$)	6,473.39	4,896.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK FRT BONNET,FRT FENDER X2,WELD,REMOVE & FIX ON ABOVE PARTS	New	700.00	400.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	800.00	750.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO APPLY ANTI RUST COATING	New	80.00	0.00
5	TO DIAGNOSE & RESET FAULT CODE	New	180.00	80.00
6	TOWING CHARGE	New	50.00	50.00
Gross Labour Cost (\$)			1,840.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >