

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006561/NPA3Q2
Date: 30/07/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070146403
Claimant Vehicle No :	SHD1405T	Insured Vehicle No :	GBE3696Y
Date of Loss:	09/06/2021	Nature of Claim:	TP
		Claim No:	6651471149SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD1405T	Engine No:	D4FBHZ172593
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	Chassis No:	TMAD281UVHJ141901
Reg. Date:	04/10/2017 (Man. Year: 2017)	Odometer:	196895 km
Colour:	Silver		
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 4 mm	Rear Left Side:	Maxxis 4 mm
Front Right Side:	Maxxis 4 mm	Rear Right Side:	Maxxis 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,497.49	842.65	1,654.84	66.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	710.00	1,060.00	59.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,267.49	1,552.65	2,714.84	63.62
Approved Total (Overridden) (S\$)		1,200.00		

Adjuster Report

	(S\$)	4,267.49	1,200.00	3,067.49	71.88
+ GST 7.00/7.00% (S\$)		298.72	84.00	214.72	71.88
Nett Amount (S\$)		4,566.21	1,284.00	3,282.21	71.88
+ Car Rental (4.5 x S\$37.41/day) (S\$)			168.35		
+ Doc/Search Fee (S\$)			2.00		
			1,454.35		
			1,450.00		

INSPECTION

Date of Assignment: 09/06/2021

Date Inspected: 10/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
23 Changi South Ave 2, #01-02
Singapore 486443**Adjuster:** Muhammad Nazril Bin Abdullah**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*TAILGATE LOWER GARNISH	Repair	362.61 FL	*- FL	
2	1		*EMBLEM I30	Necessary	27.80 FL	*27.80 FL	
3	1		*EMBLEM CRDI	Necessary	29.40 FL	*29.40 FL	
4	1		*REAR BUMPER	Cracked	811.11 FL	*811.11 FL	
5	1		*REAR BUMPER SPONGE	Serviceable	79.20 FL	*- FL	
6	1		*REAR BUMPER REINFORCEMENT	Serviceable	815.64 FL	*- FL	
7	1		*REAR BUMPER REINFORCEMENT CENTRE	Serviceable	79.20 FL	*- FL	
8	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Serviceable	104.40 FL	*- FL	
9	2		*REAR BUMPER N/S & O/S REFLECTOR	Serviceable	215.00 FL	*- FL	
10	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS	
11	1		*SET REVERSE SENSOR	Serviceable	280.00 FS	*- FS	
12	1		*SET TAILGATE STICKERS	Necessary	100.00 FS	*100.00 FS	
13	1		*SUNDRY	Not Necessary	50.00 FS	*- FS	
					Sub Total (\$)	3,002.36	1,016.31
					- List Item Discount on L Items 20.00/20.00% (\$)	504.87	173.66
					Total Parts (\$)	2,497.49	842.65

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM	New	120.00	30.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT, CARPET ,ETC TO FACILIATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE OF THE SAME ETC	New	750.00	360.00
4	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,TAILGATE LOWER GARNISH END PANEL	New	600.00	280.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	40.00
			Gross Labour Cost (S\$)	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >