

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21006565/UGS3Q2
Date: 09/09/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MFL0002083_02
Claimant Vehicle No :	FBL1663T	Insured Vehicle No :	YP1743C
Date of Loss:	19/12/2020	Nature of Claim:	TP
		Claim No:	MFL2021D0002469

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL1663T	Engine No:	122EN38170097
Make & Model:	BMW R1200 GSA, 1.2	Chassis No:	WB10A0203JZ927188
Reg. Date:	25/01/2018 (Man. Year: 2017)	Odometer:	20940 km
Colour:	Black/Grey		
Engine Capacity:	1170 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/70 R19	Rear Tyre Size:	170/60 R17
Front Left Side:	Metzeler 7 mm	Rear Left Side:	Metzeler 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,649.00	988.00	661.00	40.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	63.00	45.00	18.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,712.00	1,033.00	679.00	39.66
+ GST 7.00/7.00% (S\$)	119.84	72.31	47.53	39.66

Nett Amount (S\$)	1,831.84	1,105.31	726.53	39.66
+ Loss of Use (0.5 x S\$20.00/day) (S\$)		10.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,122.76		

INSPECTION

Date of Assignment: 09/06/2021

Date Inspected: 10/06/2021

Estimated Period of Repair: 0.5 days

Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Aug 2021)	
Parts:	N/A	BMW R1200 GSA 1.2 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL1663T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*SET BACK REST	Serviceable	216.00 F	*- F	
2	1		*BOX ALUMINIUM (BLACK)	Dented / Damaged	1,395.00 FS	*950.00 FS	
3	1		*LABEL SPEED /PAYLOAD	Necessary	38.00 FS	*38.00 FS	
					Total Parts (S\$)	1,649.00	988.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR QUOTED FOR DISMANTLING AND INSTALLTION OF PARTS	New	63.00	45.00
			Gross Labour Cost (S\$)	45.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >