



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105230

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 27/07/2021  
Reference CC3/CTI21006567/Kes3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 5343L  
Insured Veh. SLD 1323Z  
Claim No. SNM21D203203/C02  
Policy No. DMPCSNW00160732000  
Accident Date 04/06/2021  
Inspection Date 08/06/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21006567/Kes3q2	
			Date: 27/07/2021	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLD 1323Z	Veh. Inspected	SHD 5343L	
Policy No.	DMPCSNW00160732000	Coverage (\$)	0.00	
Claim No.	SNM21D203203/C02	Excess (\$)	0.00	
Assign From		Assign Date	08/06/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU203078888	Colour	M . P. WHITE / RED	
Odometer	170819 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SAILUN	9 mm	
L/H Front Tyre	195/65 R15	SAILUN	9 mm	
R/H Rear Tyre	195/65 R15	SAILUN	9 mm	
L/H Rear Tyre	195/65 R15	SAILUN	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	04/06/2021	Inspection Date	08/06/2021	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			1.500 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5343L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	LENS AND BODY ,REAR LAMP ,RH	SERVICEABLE	502.00	-
1	LENS & BODY ,REAR COMBINATION LAMP ,RH	SERVICEABLE	451.80	-
1	FENDER SUB-ASSY ,FRONT RH	TO REPAIR SEE LABOUR	977.80	-
1	PANEL SUB-ASSY ,QUARTER ,RH	TO REPAIR SEE LABOUR	871.50	-
1	LINER ,REAR WHEEL HOUSE , RH	SERVICEABLE	139.80	-
1	COVER ,REAR BUMPER	TO REPAIR SEE LABOUR	442.60	-
1	FILLER ,REAR BUMPER EXTENSION ,RH	SERVICEABLE	123.70	-
1	GUARD ,REAR BUMPER ,CENTER	SERVICEABLE	576.30	-
1	REINFORCEMENT SUB-ASSY ,REAR BUMPER	TO REPAIR SEE LABOUR	332.70	-
	LESS 25% DISCOUNT		-1,104.55	-
			3,313.65	-
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FENDER LINER CLIP (SN)	NOT NECESSARY	75.00	-
1	FENDER CLIP (SN)	NOT NECESSARY	75.00	-
1	REAR BUMPER CLIP (SN)	NOT NECESSARY	65.00	-
1	END PANEL INNER TRIM CLIP (SN)	NOT NECESSARY	60.00	-
1	TYRE (SN)	SERVICEABLE	350.00	-
1	RIM (SN)	SERVICEABLE	1,879.40	-
1	HUM CAP (SN)	SERVICEABLE	211.50	-
			2,715.90	-
<b><u>LABOUR</u></b>				
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS .	NOT NECESSARY	250.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		1,800.00	440.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED .	NOT NECESSARY	170.00	-

Report Ref No. CC3/CTI21006567/Kes3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FENDER SUB-ASSY ,FRONT RH,PANEL SUB-ASSY ,QUARTER ,RH ,COVER ,REAR BUMPER AND REINFORCEMENT SUB-ASSY ,REAR BUMPER .		1,800.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT .	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR FENDER PANEL FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST .	NOT NECESSARY	170.00	-
			4,790.00	540.00
<b>GRAND TOTAL</b>			<b>10,819.55</b>	<b>540.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>540.00</b>

Report Ref No. CC3/CTI21006567/Kes3q2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 5343L

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

