

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21006568/KPA3Q2**Date:** 26/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100478383
<b>Claimant Vehicle No :</b>	SHC5047Y	<b>Insured Vehicle No :</b>	SLE9914K
Date of Loss:	07/06/2021	Nature of Claim:	TP
		Claim No:	7910809442SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC5047Y</b>		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZR2H15904
Reg. Date:	06/11/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU703092639
Colour:	Metallic Pearl White/Red	Odometer:	55888 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,156.07	1,358.92	4,797.15	77.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,840.00	800.00	4,040.00	83.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>10,996.07</b>	<b>2,158.92</b>	<b>8,837.15</b>	<b>80.37</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment:	08/06/2021	
Date Inspected:	08/06/2021	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*GUARD ,REAR BUMPER CENTER	Dented / Cut	374.50 FL	*374.50 FL
4	1		*COVER ,REAR BUMPER ,LOWER	Dented	22.00 FL	*22.00 FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	132.60 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	132.60 FL	*- FL
7	1		*REFLECTOR ASSY ,REFLEX ,LH	Serviceable	39.00 FL	*- FL
8	1		*REFLECTOR ASSY ,REFLEX ,RH	Serviceable	39.00 FL	*- FL
9	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
10	1		*COVER ,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
11	1		*COVER FLOOR UNDER NO.2 (RH)	Serviceable	241.90 FL	*- FL
12	1		*COVER FLOOR UNDER NO.1 (LH)	Serviceable	175.10 FL	*- FL
13	1		*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
14	1		*PANEL SUB-ASSY ,BACK DOOR	Repair	1,147.80 FL	*- FL
15	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Repair	913.60 FL	*- FL
16	1		*STAY ASSY ,BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
17	1		*STAY ASSY ,BACK DOOR ,RH	Serviceable	242.50 FL	*- FL
18	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
19	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- FL
20	1		*ORNAMENT SUB-ASSY ,BACK DOOR	Necessary	47.90 FL	*47.90 FL
21	1		*PLATE ,LUGGAGE COMPARTMENT DOOR NAME ,NO.2	Necessary	54.60 FL	*54.60 FL
22	1		*PLATE ,BACK DOOR NAME NO.1	Necessary	54.60 FL	*54.60 FL
23	1		*SET PARKING AID	Dented / Scratched	700.00 FS	*220.00 FS
24	1		*SET REAR BUMPER CLIP	Necessary	85.00 FS	*50.00 FS
25	1		*BUMPER CENTRE GUARD CLIP	Not Necessary	80.00 FS	*- FS
26	1		*REAR BUMPER PROTECTOR	No such part	180.00 FS	*- FS
27	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
28	1		*BOOT STICKER TRANSCAB	Necessary	100.00 FS	*30.00 FS
29	1		*BOOT STICKER 6555-3333	Necessary	100.00 FS	*30.00 FS
30	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
31	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
32	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,608.10</b>	<b>1,701.90</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	1,452.03	342.98
<b>Total Parts (\$)</b>	<b>6,156.07</b>	<b>1,358.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	300.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	440.00
6	TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,840.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >