

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21006571/ARS3Q2
Date: 17/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800092319
Claimant Vehicle No :	SMY8967Y	Insured Vehicle No :	SMD704C
Date of Loss:	04/06/2021	Nature of Claim:	TP
		Claim No:	8325829183SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY8967Y	Engine No:	10Z1AF0031069
Make & Model:	OPEL CORSA, 1.2 EASYTRONIC (A)	Chassis No:	VXKUPHNSSL4280811
Reg. Date:	29/03/2021 (Man. Year: 2020)	Odometer:	3545 km
Colour:	Grey		
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,383.40	5,654.00	6,729.40	54.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,990.00	1,650.00	2,340.00	58.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,373.40	7,304.00	9,069.40	55.39
+ GST 7.00/7.00% (S\$)	1,146.14	511.28	634.86	55.39

Nett Amount (S\$)	17,519.54	7,815.28	9,704.26	55.39
		+ Car Rental (7.0 x S\$100.00/day) (S\$)	700.00	
		+ Doc/Search Fee (S\$)	7.45	
		Nett Liability (S\$)	8,522.73	

INSPECTION

Date of Assignment: 09/06/2021

Date Inspected: 09/06/2021

Estimated Period of Repair: 5.0 days

Inspected At: Xin Hua Workshop Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01
Singapore 415933

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Torn	1,597.00 FL	*1,597.00 FL
2	1		*RR BUMPER SIDE RETAINER RH (OUTER)	Cracked	199.00 FL	*199.00 FL
3	1		*RR BUMPER REFLECTOR COVER RH	Not Necessary	220.00 FL	*- FL
4	1		*SET RR BUMPER PARKING SENSOR HOLDER	Necessary	239.00 FL	*239.00 FL
5	1		*RR BUMPER BLIND SPOT SENSOR HOLDER	Necessary	233.00 FL	*233.00 FL
6	1		*RR BUMPER BLIND SPOT SENSOR	Not Necessary	316.00 FL	*- FL
7	1		*RR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	360.00 FL	*- FL
8	1		*RR BUMPER MUD FLAT RH	Cut	216.00 FL	*216.00 FL
9	1		*RR TAILLAMP RH	Not Necessary	631.00 FL	*- FL
10	1		*RR BUMPER REFLECTOR RH	Not Necessary	126.00 FL	*- FL
11	1		*RR FENDER RH	Buckled	1,951.00 FL	*1,951.00 FL
12	1		*RR FENDER INNER SHIELD RH	Torn	321.00 FL	*321.00 FL
13	1		*RR WHEELHOUSE PANEL RH	Repair	1,531.00 FL	*- FL
14	1		*RR FENDER TOP GARNISH RH	Not Necessary	192.00 FL	*- FL
15	1		*RR RIM RH	Cut	898.00 FL	*898.00 FL
16	1		*RR RIM CAP RH- GREY	Cut	157.00 FL	*157.00 FL
17	1		*RR ABS SENSOR	Not Necessary	387.00 FL	*- FL
18	1		*RR SHOCK ABSORBER RH	Not Necessary	444.00 FL	*- FL
19	1		*RR SHOCK ABSORBER TOP MOUNTING RH	Not Necessary	182.00 FL	*- FL
20	1		*RR SHOCK ABSORBER DUST COVER RH	Not Necessary	211.00 FL	*- FL
21	1		*RR WHEEL BEARING RH	Damaged	349.00 FL	*349.00 FL
22	1		*RR AXLE ASSY	Not Necessary	2,216.00 FL	*- FL
23	1		*RR NUMBER PLATE WITH COVER	Not Necessary	65.00 FS	*- FS
24	10		*RR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
25	10		*RR FENDER INNER SHIELD CLIP	Not Necessary	60.00 FS	*- FS
26	10		*RR FENDER PROTECTOR CLIP	Not Necessary	60.00 FS	*- FS
27	1		*RR TYRE RH	Not Necessary	350.00 FS	*- FS
28	1		*BODY PANEL JOINT SEALER	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,681.00	6,270.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,297.60	616.00
Total Parts (\$)	12,383.40	5,654.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE STRAIGHTEN ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,200.00	600.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA ,RR DOOR RH ,RR FENDER RH RR BUMPER	New	1,200.00	600.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	80.00	50.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	120.00	30.00
5	REMOVE AND REFIX SEAT CUSHION /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	200.00	60.00
6	TO REMOVE AND REFIX REAR SENSOR AND CONDUCT TEST	New	100.00	50.00
7	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	100.00	0.00
8	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	60.00	0.00
9	REMOVE AND REPLACE RHR UNDER CARRIAGE PARTS	New	400.00	80.00
10	TO CONDUCT 4 WHEEL ALIGNMENT	New	180.00	80.00
11	TO PERFORM DIAGNOSSIS RESET ON FAULTY CODE	New	350.00	100.00
Gross Labour Cost (\$\$)			3,990.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >