



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Ref: CC4/ASM21006572/Aba3q2 Date: 08/10/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3889S	Veh. Inspected	SJQ 2971B
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M03BBI	Excess (\$)	0.00
	Assign From		Assign Date	09/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	MINI COOPER S	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	WMWMS32050TJ92649	Colour	RED
	Odometer	122981 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/45 R17	MICHELIN	6 mm
	L/H Front Tyre	205/45 R17	MICHELIN	6 mm
	R/H Rear Tyre	205/45 R17	MICHELIN	6 mm
	L/H Rear Tyre	205/45 R17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/06/2021	Inspection Date	09/06/2021
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	