

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006577/AQCN2**Date:** 30/08/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00054222100

**Claimant Vehicle
No :** SMM5665B**Insured Vehicle
No :** SKS69Y

Date of Loss: 08/06/2021

Nature of Claim: TP

Claim
No: SNM21D203270/C2/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMM5665B**

Make & Model: HONDA SHUTTLE, 1.5 (A)

Engine No: L15B6001970

Reg. Date: 04/07/2019 (Man. Year: 2019)

Chassis No: GK82001630

Colour: Grey

Odometer: 66309 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,072.88	3,946.64	9,126.24	69.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,480.00	2,380.00	4,100.00	63.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,552.88	6,326.64	13,226.24	67.64
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	19,552.88	5,000.00	14,552.88	74.43

INSPECTION

Date of Assignment: 10/06/2021

Date Inspected: 10/06/2021 Inspected At:

Ishare Auto Pte. Ltd. (HQ)

8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @

KAKI BUKIT

Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Aug 2021)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM5665B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE SKIRT RH	Cracked	393.20 FL	*393.20 FL
2	1		*FRONT DOOR SIDE MIRROR RH	Cut	754.30 FL	*754.30 FL
3	1		*FRONT DOOR RH	Dented	1,267.80 FL	*1,150.00 FL
4	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	386.20 FL	*- FL
5	2		*FRONT DOOR HINGE RH	Not Necessary	99.60 FL	*- FL
6	1		*FRONT DOOR CHECKER RH	Not Necessary	106.40 FL	*- FL
7	1		*FRONT DOOR GLASS CHANNEL RH	Not Necessary	84.30 FL	*- FL
8	1		*FRONT DOOR BOTTOM WEATHER STRIP RH	Not Necessary	89.40 FL	*- FL
9	1		*FRONT DOOR INNER LOCK RH	Damaged	297.50 FL	*297.50 FL
10	1		*FRONT DOOR FRAME WEATHER STRIP RH	Not Necessary	167.40 FL	*- FL
11	1		*FRONT DOOR OUTER STRIP RH	Not Necessary	96.70 FL	*- FL
12	1		*FRONT DOOR LOCK CATCH RH	Not Necessary	20.10 FL	*- FL
13	1		*FRONT DOOR INNER TRIM BOARD RH	Cracked	649.80 FL	*495.00 FL
14	1		*FRONT DOOR REGULATOR RH	Damaged	353.50 FL	*353.50 FL
15	1		*FRONT DOOR POWER WINDOW MOTOR RH	Not Necessary	459.60 FL	*- FL
16	1		*FRONT DOOR OUTER KEY LOCK RH	Not Necessary	168.70 FL	*- FL
17	1		*FRONT DOOR SPEAKER RH	Not Necessary	197.60 FL	*- FL
18	2		*FRONT DOOR STOPPER RH	Not Necessary	37.80 FL	*- FL
19	1		*CENTER PILLAR GARNISH RH (INNER)	Not Necessary	321.60 FL	*- FL
20	1		*REAR DOOR RH	Dented	986.70 FL	*986.70 FL
21	1		*REAR DOOR GLASS CHANNEL RH	Not Necessary	82.40 FL	*- FL
22	1		*REAR DOOR POWER WINDOW MOTOR RH	Not Necessary	598.70 FL	*- FL
23	1		*REAR DOOR FRAME WEATHER STRIP RH	Not Necessary	176.40 FL	*- FL
24	1		*REAR DOOR INNER LOCK RH	Not Necessary	264.70 FL	*- FL
25	1		*REAR DOOR INNER TRIM RH	Not Necessary	765.80 FL	*- FL
26	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	184.80 FL	*- FL
27	1		*REAR DOOR OUTER MOULDING RH	Not Necessary	127.10 FL	*- FL
28	1		*REAR DOOR BOTTOM WEATHERSTRIP RH	Not Necessary	79.60 FL	*- FL
29	2		*REAR DOOR HINGE RH	Not Necessary	99.60 FL	*- FL
30	1		*REAR DOOR CHECKER RH	Not Necessary	106.40 FL	*- FL
31	1		*REAR DOOR FRONT WEATHER STRIP RH	Not Necessary	158.60 FL	*- FL
32	1		*REAR DOOR LOCK CATCH RH	Not Necessary	20.10 FL	*- FL
33	1		*REAR DOOR SPEAKER RH	Not Necessary	197.60 FL	*- FL
34	1		*REAR DOOR GLASS REGULATOR GEAR RH	Damaged	353.10 FL	*353.10 FL
35	1		*REAR FENDER COWLING RH	Not Necessary	197.90 FL	*- FL
36	1		*REAR WHEEL CAP RH	Not Necessary	186.40 FL	*- FL
37	1		*REAR ABS SENSOR RH	Not Necessary	265.40 FL	*- FL
38	1		*REAR AXLE	Not Necessary	1,080.60 FL	*- FL
39	1		*REAR WHEEL HUB C/W BEARING RH	Not Necessary	371.40 FL	*- FL
40	1		*REAR SHOCK ABSORBER RH	Not Necessary	350.60 FL	*- FL
41	1		*REAR BUMPER	Not Necessary	1,150.60 FL	*- FL
42	2		*REAR BUMPER SIDE RETAINER	Not Necessary	74.80 FL	*- FL
43	2		*FRONT DOOR GLASS FRAME BLACK STICKER RH	Necessary	158.24 FS	*60.00 FS
44	1		*SET SIDE SKIRT CLIP RH	Necessary	80.00 FS	*30.00 FS
45	1		*SET FRONT DOOR TRIM BOARD CLIP	Necessary	80.00 FS	*30.00 FS
46	1		*SET CENTER PILLAR GARNISH CLIP RH	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET REAR DOOR INNER TRIM CLIP RH	Not Necessary	80.00 FS	*- FS
48	1		*SET REAR FENDER COWLING CLIP RH	Not Necessary	80.00 FS	*- FS
49	1		*SET REAR BUMPER CLIP	Not Necessary	80.00 FS	*- FS
50	1		*REAR WHEEL RIM RH	Not Necessary	850.00 FS	*- FS
51	1		*REAR WHEEL TYRE LH	Not Necessary	480.00 FS	*- FS
52	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,839.04	4,903.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,766.16	956.66
Total Parts (\$\$)	13,072.88	3,946.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT,WELD,CUT,ADJUST,KNOCK	New	1,800.00	800.00
2	TO SPRAY PAINT	New	1,800.00	1,300.00
3	TUFF COAT	New	250.00	60.00
4	WIRING,BULB CHECKING	New	80.00	0.00
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	450.00	60.00
6	TRANSFER FRONT DOOR MECHANISM RH	New	80.00	80.00
7	REMOVE & REFIX FRONT DOOR AUDIO SPEAKER	New	120.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	0.00
9	TRANSFER REAR DOOR MECHANISM	New	80.00	80.00
10	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
11	CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
12	RESET ABS LIGHT	New	350.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	550.00	0.00
Gross Labour Cost (\$\$)			6,480.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >