

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21006578/VVF3Q2
Date: 23/06/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	EX9669B	Insured Vehicle No :	SKG2570R
Date of Loss:	08/06/2021	Nature of Claim:	TP
		Claim No:	9267079008SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EX9669B		
Make & Model:	HONDA ACCORD, 1.6 (M)	Engine No:	L15B3537465
Reg. Date:	13/10/2016 (Man. Year: 2016)	Chassis No:	GK81006353
Colour:	Blue	Odometer:	53997 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

6/23/2021

Adjuster Report

Date of Assignment: 10/06/2021

Date Inspected: 10/06/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Everdawn Auto Service (KAKI BUKIT)
8 Kaki Bukit Ave 4, #01-02 Premier @ Kaki Bukit
Singapore 415875

Adjuster: Thevan Thomas Karthikesavan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$59,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Dented	0.00 F	*- F	
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
3	1		*REAR BUMPER SPONGE (RH)	Cut	0.00 F	*- F	
4	1		*REAR END PANEL	Repair	0.00 F	*- F	
5	1		*TAILGATE	Dented	0.00 F	*- F	
6	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F	
7	1		*TAILGATE MOULDING	Cracked	0.00 F	*- F	
8	1		*TAILGATE GARNISH	Cracked	0.00 F	*- F	
9	2		*TAILGATE LAMP	Cracked	0.00 F	*- F	
10	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F	
11	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F	
12	1		*TAILGATE RUBBER	Cut	0.00 F	*- F	
13	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F	
14	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F	
15	1		*BUMPER REFLECTOR COVER (RH)	Cracked	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >