

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006587/EGA3Q2
Date: 05/01/2022

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070144080
Claimant Vehicle No :	SMS6302K	Insured Vehicle No :	SMV5910X
Date of Loss:	07/06/2021	Nature of Claim:	TP
		Claim No:	6832724270SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS6302K		
Make & Model:	NISSAN LATIO, 1.5 L (A)	Engine No:	HR15237598A
Reg. Date:	09/05/2008 (Man. Year: 2007)	Chassis No:	JN1BAAC11Z0007599
Colour:	Gold	Odometer:	215335 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,860.00	2,502.81	5,357.19	68.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,000.00	1,830.00	3,170.00	63.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,860.00	4,332.81	8,527.19	66.31
Approved Total (Overridden) (S\$)		3,450.00		

Nett Amount (S\$)	12,860.00	3,450.00	9,410.00	73.17
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,057.45		
Global Sum Settlement (S\$)		4,000.00		

INSPECTION

Date of Assignment: 10/06/2021

Date Inspected: 10/06/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Auburn Auto Pte Ltd (HQ)
 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE
 Singapore 575721

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR	Broken	200.00 F	*200.00 FL
2	1		*RIGHT TAIL LIGHT BRACKET	Not Necessary	120.00 F	*- FL
3	1		*END PANEL GARNISH	Broken	230.00 F	*182.00 FL
4	1		*TAIL LAMP LOWER BRACKET	Not Necessary	120.00 F	*- FL
5	1		*REAR RIGHT BUMPER RETAINER (R&L)	Broken	180.00 F	*156.00 FL
6	1		*REAR RIGHT TAILLIGHT BRACKET	Not Necessary	120.00 F	*- FL
7	1		*REAR LEFT TAILLIGHT BRACKET	Not Necessary	120.00 F	*- FL
8	1		*REAR RIGHT WHEEL BEARING	Not Necessary	150.00 F	*- FL
9	1		*REAR LEFT WHEEL BEARING	Not Necessary	150.00 F	*- FL
10	1		*SPARE TYRE BOARD	Not Necessary	80.00 F	*- FL
11	1		*BOOTLID WEATHERSTRIP	Torn	350.00 F	*148.00 FL
12	1		*BUMPER BRACKET	Not Necessary	150.00 F	*- FL
13	1		*REAR RIGHT ABSORBER	Not Necessary	230.00 F	*- FL
14	1		*REAR LEFT ABSORBER (FOAM)	Missing	230.00 F	*57.00 FL
15	1		*REAR RIGHT MUDGUARD	Not Necessary	80.00 F	*- FL
16	1		*REAR LEFT MUDGUARD	Not Necessary	80.00 F	*- FL
17	1		*LEFT BOOTLID LAMP	Not Necessary	200.00 F	*- FL
18	1		*RIGHT BOOTLID LAMP	Not Necessary	200.00 F	*- FL
19	1		*LEFT TAIL LIGHT	Not Necessary	200.00 F	*- FL
20	1		*RIGHT TAIL LIGHT	Not Necessary	200.00 F	*- FL
21	1		*BOOT LOCK	Bent	350.00 F	*97.90 FL
22	1		*REAR UNDERCARRIAGE	Not Necessary	900.00 F	*- FL
23	1		*BOOT LID	Dented	1,400.00 F	*787.00 FL
24	2		*BOOT LID BADGE	Necessary	120.00 F	*120.00 FL
25	1		*BOOT CHROME GARNISH	Not Necessary	250.00 F	*- FL
26	1		*REAR BUMPER	Broken	650.00 F	*551.00 FL
27	1		*END PANEL	Dented	800.00 F	*482.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	7,860.00	2,780.90
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	278.09
Total Parts (\$)	7,860.00	2,502.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECKING OF WIRING ,LIGHTING AND RESETTNG	New	300.00	30.00
2	REMOVE AND REFIT REAR UNDERCARRIAGE	New	500.00	0.00
3	WHEEL ALIGNMENT	New	100.00	0.00
4	REMOVE AND REPLACE DAMAGED PARTS	New	800.00	0.00
5	APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	800.00	0.00
6	WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS ,REPAIRS INCLUDING CUT AND WIELD ,REALIGN BODY STRUCTURE	New	1,500.00	800.00
7	RESPRAY INCLUDING POLISHING AND WAXING ON THE CHARGED BODY PARTS ,REPAIRED PORTORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	1,000.00
Gross Labour Cost (\$\$)			5,000.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >