



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GT 3348P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	496.00	496.00
1	FRONT BUMPER SIDE RETAINER LH	DAMAGED	149.00	149.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	304.00	-
1	FRONT BUMPER FOG LAMP GARNISH LH	NOT NECESSARY	58.00	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	155.00	-
1	LH FRONT HEADLAMP	CRACKED	850.00	850.00
1	LH FRONT CORNER PANEL	DENTED	220.00	220.00
1	LH FRONT CORNER INNER PANEL BRACKET	BENT	20.00	20.00
1	BONNET	DENTED	750.00	750.00
1	BONNET HINGE LH	NOT NECESSARY	78.00	-
1	WIPER TANK	NOT NECESSARY	58.00	-
1	WIPER GARNISH LH	NOT NECESSARY	495.00	-
1	LH FRONT DOOR	TO REPAIR SEE LABOUR	1,700.00	-
2	LH FRONT DOOR HINGE @\$78.00	NOT NECESSARY	156.00	-
1	LH FRONT DOOR CHECKER	NOT NECESSARY	150.00	-
1	FRONT GRILLE TOP	CRACKED	191.00	191.00
1	FRONT GRILLE BOTTOM	CRACKED	330.00	290.00
1	FRONT GRILLE BASE	CRACKED	490.00	450.00
1	FRONT GRILLE TOP GARNISH	NOT NECESSARY	150.00	-
	LESS 25% DISCOUNT		-1,700.00	-854.00
			5,100.00	2,562.00
<u>SPECIAL NETT ITEMS</u>				
1	LH FRONT DOOR STICKER (SN)	NECESSARY	25.00	25.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	FRONT GRILLE CLIPS (SN)	NECESSARY	60.00	20.00
			165.00	75.00
<u>LABOUR</u>				
	LABOUR FOR PANEL BEATING.INCLUSIVE OF THE REPAIR OF LH FRONT DOOR.		1,000.00	600.00
	LABOUR FOR SPRAYPAINTING.		800.00	600.00

Report Ref No. CS/SMR21006591/Auf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHECK.		80.00	30.00
	TO APPLY RUST PROOF/TUFF COAT ON ACCIDENT AREAS.		200.00	40.00
	LABOUR FOR REMOVE & TRANSFER FRONT LH DOORS FITTING.	NOT NECESSARY	200.00	-
			2,280.00	1,270.00
	GRAND TOTAL		7,545.00	3,907.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00

Report Ref No. CS/SMR21006591/Auf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.