



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 5245L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED / TORN	1,852.50	1,240.00
1	FRONT BUMPER RH FOG LAMP COVER	BROKEN / CUT	124.95	124.95
1	FRONT BUMPER RH CORNER SMALL ARCH COVER	DEFORMED	92.35	92.35
2	FRONT BUMPER PARKING SENSOR	SERVICEABLE	549.94	-
4	FRONT BUMPER PARKING SENSOR HOLDER	BROKEN / NECESSARY	240.40	240.40
1	FRONT BUMPER RH INNER SMALL	BENT	92.35	92.35
1	FRONT BUMPER RH SIDE HOLDER	DEFORMED / BROKEN	79.20	79.20
1	FRONT BUMPER INNER FOAM	TORN	178.75	178.75
1	FRONT BUMPER INNER REINFORCEMENT	DENTED / BENT	721.00	721.00
1	FRONT BUMPER INNER REINFORCEMENT RH CORNER LOWER SMALL BRACKET	DENTED / BENT	20.53	20.53
1	HORN	BROKEN / MALFUNCTION	187.95	187.95
1	RH HID HEADLAMP	BROKEN / SMASHED	3,856.20	2,653.00
1	RH HID HEADLAMP BALLAST	SERVICEABLE	633.80	-
1	RH HID HEADLAMP TOP ALUMINIUM BRACKET	SERVICEABLE	82.60	-
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	966.68	-
1	FRONT RH FENDER UNDER SPLASH SHIELD	SERVICEABLE	191.61	-
1	SET FRONT FENDER UNDER SPLASH SHIELD CLIPS	NOT NECESSARY	50.00	-
	LESS 10% DISCOUNT		-992.08	-563.05
			8,928.73	5,067.43
	<u>LABOUR</u>			
	TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT RH FENDER.		1,000.00	400.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		1,000.00	500.00
	TO CHECK WIRINGS & RESET LIGHTINGS.		80.00	30.00
	TO REMOVE, REFIX AND RESET FRONT BUMPER PARKING SENSORS.		120.00	60.00

Report Ref No. CS3/AIG21005984/R1qf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REFILL AIRCON CONDENSER, PIPES, DRIER VACUUM AND RECHARGE GAS.	NOT NECESSARY	120.00	-
	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS.	NOT NECESSARY	100.00	-
			2,420.00	990.00
GRAND TOTAL			11,348.73	6,057.43
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,850.00

Report Ref No. CS3/AIG21005984/R1qf3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.