

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 14 Jun 2021

Preliminary Advice

Insured Vehicle No	: SME7896E	Accident Date	: 08/06/2021
TP Vehicle No	: SLE97C	Assignment Date	: 10/06/2021
Make	: BMW 318i	Est. Duration of Repair	: 6
Date of Inspection	: 10/06/2021		
Inspection At	: MOVA AUTOMOTIVE PTE LTD (FAN YOONG BRANCH) 15 FAN YOONG ROAD, CNG SINGAPORE CENTRE SINGAPORE 629792		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,460.15
Revised Amount	:S\$	4,484.25
Check Items (Estimated)	:S\$	698.86
Total	:S\$	5,183.11

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :