

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR IN	ISPECTION REPOF	RT	
	AXA INSURANCE	PTE LTD	Ref	: CS3/ASM21006597/Vqce2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Dat	e: 23/06/2021	
	ATTN: ANG RICHA	ARD	Cod	de: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 3504C	Veh. Inspected	SJX 3767G	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M03BFQ	Excess (\$)	0.00	
	Assign From	ANG RICHARD	Assign Date	10/06/2021	
2.	•	Vehicle P	articulars & Condition		
	Make & Model	TOYOTA COROLLA ALTIS 1	.6A c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	MR053ZEE106175443	Colour	WHITE	
	Odometer	226861 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	FALKEN	4 mm	
	L/H Front Tyre	205/55 R16	FALKEN	4 mm	
	R/H Rear Tyre	205/55 R16	FALKEN	4 mm	
	L/H Rear Tyre	205/55 R16	FALKEN	4 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND REAR N/S PORTION.				
5.	General Information				
	Accident Date	06/06/2021	Inspect Date / Time	e 10/06/2021 (04:36 PM)	
	Survey held at	3 MOTORWERKZ			
	25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$14,000-\$15,000				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 18 Working Days			

Report Ref No. CS3/ASM21006597/Vqce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser