

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	AXA INSURANCE I	PTE LTD	Ref:	CS3/ASM21006600/Vvce2
	8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date	17/06/2021
	ATTN: KITTY TEO		Code	e: ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SMF 2347B	Veh. Inspected	SJF 7080Y
	Policy No.	GA554945	Coverage (\$)	0.00
	Claim No.	S1M03BKL	Excess (\$)	0.00
	Assign From	KITTY TEO	Assign Date	10/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 8 2.3L	c.c	2261
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	JM6LY1033D0300346	Colour	BLACK
	Odometer	175221 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/65 R16	MICHELIN	6 mm
	L/H Front Tyre	215/65 R16	MICHELIN	6 mm
	R/H Rear Tyre	215/65 R16	MICHELIN	6 mm
	L/H Rear Tyre	215/65 R16	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5.	General Information			
	Accident Date	08/06/2021	Inspect Date / Time	11/06/2021 (10:25 AM)
	Survey held at	160 SIN MING DRIVE #01-07 SII	N MING AUTO CITY	
	Repairer INFINITY COACH & TRADING PTE LTD			
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			

Report Ref No. CS3/ASM21006600/Vvce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser