

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7218B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	458.60	-
1	REAR BUMPER LOWER COVER BLACK	SERVICEABLE	552.60	-
10	REAR BUMPER CLIPS @\$2.20	SERVICEABLE	22.00	-
	LESS 25% DISCOUNT		-258.30	-
			774.90	-
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
			135.70	-
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			820.00	630.00
GRAND TOTAL			1,730.60	630.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				630.00

Report Ref No. NS/INC21006604/Nvcn2



MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.