

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8276H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	CRACKED	1,106.00	1,106.00
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE BRACKET RH	SERVICEABLE	35.60	-
1	REAR BUMPER REFLECTOR LAMP RH	SERVICEABLE	32.00	-
1	TAIL LAMP RH	CRACKED	697.80	697.80
	LESS 20% DISCOUNT		-378.68	-365.16
			1,514.72	1,460.64
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER ADVERTISEMENT STICKER (SN)	NECESSARY	50.00	50.00
1	REAR FENDER ADVERTISEMENT STICKER RH (SN)	NECESSARY	100.00	100.00
			150.00	150.00
<u>LABOUR</u>				
	WIRING CHARGE.	NOT NECESSARY	60.00	-
	TUFF KOTE.		60.00	40.00
	PANEL BEATING.		350.00	280.00
	SPRAY PAINTING CHARGE.		500.00	250.00
			970.00	570.00
GRAND TOTAL			2,634.72	2,180.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,750.00

Report Ref No. NS/INC21006609/Nqce2


MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor


K.K.LAU CPT(RET)
**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**
REGD Auto Consultant-SAE, Licensed Appraiser
DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.