

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006610/KVCN2**Date:** 19/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00039372102
Claimant Vehicle No :	SLP7658E	Insured Vehicle No :	GBB4643J
Date of Loss:	10/06/2021	Nature of Claim:	TP
		Claim No:	SNM21D203297/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7658E	Engine No:	P520444932
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Chassis No:	JM6BN22A8H0153234
Reg. Date:	16/06/2017 (Man. Year: 2017)	Odometer:	142373 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,498.00	2,567.00	931.00	26.62
Miscellaneous Items	590.00	590.00	0.00	0.00
Labour	4,080.00	2,960.00	1,120.00	27.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	8,168.00	6,117.00	2,051.00	25.11
+ GST 7.00/7.00% (\$\$)	571.76	428.19	143.57	25.11
Nett Amount (\$\$)	8,739.76	6,545.19	2,194.57	25.11

INSPECTION

Date of Assignment:	14/06/2021	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	11/06/2021	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	9.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Oct 2021)
Parts:	143	MAZDA 3 1.5 SEDAN AT EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP7658E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*1 PC REAR BUMPER	Bent	390.00 F	*390.00 F
2	1	*1 PC REAR BUMPER REINFORCEMENT	Bent	210.00 F	*210.00 F
3	1	*2 PCS REAR BUMPER TOW COVERS @12/PC	N/s Missing	24.00 F	*12.00 F
4	1	*2 PCS REAR BUMPER REFLECTORS @25/PC	Serviceable	50.00 F	*- F
5	1	*2 PCS REAR BUMPER REVERSE SENSORS @90/PC	Repeated	180.00 F	*- F
6	1	*6 PCS REAR BUMPER CLIPS @2/PC	Necessary	12.00 F	*12.00 F
7	1	*1 PC REAR BOOT	Bent	420.00 F	*420.00 F
8	1	*1 PC REAR BOOT LOGO	Necessary	23.00 F	*23.00 F
9	1	*1 PC REAR BOOT EMBLEM (MAZDA 3)	Necessary	18.00 F	*18.00 F
10	1	*1 PC REAR BOOT EMBLEM (SKYACTIV)	Necessary	18.00 F	*18.00 F
11	1	*1 PC REAR BOOT INNER LOCK	Dented	95.00 F	*95.00 F
12	1	*2 PCS REAR BOOT REFLECTORS @135/PC	N/s Cracked/O/s Serviceable	270.00 F	*135.00 F
13	1	*1 PC REAR BOOT INNER RUBBER	Distorted/Dented	80.00 F	*80.00 F
14	1	*1 PC REAR BOOT NUMBER PLATE LAMP	Dented	20.00 F	*20.00 F
15	1	*2 PCS REAR BOOT HINGES @68/PC	Repair	136.00 F	*- F
16	1	*2 PCS TAILLAMPS @185/PC	N/s Cracked/O/s Serviceable	370.00 F	*185.00 F
17	1	*1 PC REAR CENTRE PANEL	Bent	210.00 F	*210.00 F
18	1	*1 PC REAR CENTRE PANEL INNER TOP GARNISH	Distorted	55.00 F	*55.00 F
19	1	*1 PC REAR SPARE TYRE HOLDER	Serviceable	38.00 F	*- F
20	1	*8 PCS REAR BOOT INNER SPONGE CLIPS @3/PC	Necessary	24.00 F	*24.00 F
21	1	*1 PC FRT BUMPER	Bent	350.00 F	*350.00 F
22	1	*1 PC FRT BUMPER REINFORCEMENT	Repair	195.00 F	*- F
23	1	*1 PC FRT BUMPER LH SIDE RETAINER	Distorted	12.00 F	*12.00 F
24	1	*7 PCS FRT BUMPER TOP CLIPS @3.5/PC	Necessary	24.50 F	*24.50 F
25	1	*7 PCS FRT BUMPER TOP CLIPS SMALL @2.5/PC	Necessary	17.50 F	*17.50 F
26	1	*1 PC FRT GRILLE	Cracked	68.00 F	*68.00 F
27	1	*1 PC FRT GRILLE LOGO	Cracked	32.00 F	*32.00 F
28	1	*1 PC FRT GRILLE MOULDING	Cracked	85.00 F	*85.00 F
29	1	*2 PCS FRT GRILLE CLIPS @18/PC	Necessary	36.00 F	*36.00 F
30	1	*1 PC FRT NUMBER PLATE GARNISH	Dented	35.00 F	*35.00 F

F=Franchise part.

Total Parts (\$\$) **3,498.00** **2,567.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC FRT NUMBER PLATE (Cracked)	35.00	35.00
2	1	1 PC REAR NUMBER PLATE (Distorted)	35.00	35.00
3	1	1 PC REVERSE CAMERA (Shorted)	320.00	320.00
4	1	1 SET REVERSE SENSOR (Dented)	200.00	200.00
Sub Total (\$\$)			590.00	590.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, CUT, WELD & RENEW REAR END PANEL, KNOCK & REPAIR REAR FENDER, REAR SPARE COMPARTMENT, REAR BOTH CHASSIS, TAILLAMP PANELS & REALIGN THE SAME	New	1,300.00	900.00
2	PUTTY & RESPRAY REAR BOOT, HINGES, REAR PANEL, TAILLAMP PANELS, REAR BUMPER, BOTH FENDERS, REAR SPARE TYRE COMPARTMENT & REAR AFFECTED AREAS	New	1,200.00	1,100.00
3	REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS, GRILLE, RADIATOR & MOTOR, TO STRAIGHTEN, KNOCK & REPAIR FRT SUPPORT PANEL & REALIGN THE SAME	New	600.00	400.00
4	PUTTY & RESPRAY FRT BUMPER, SUPPORT PANEL, BONNET, FRT FENDERS	New	800.00	500.00
5	REMOVE & REFIX AIR-CON, CHECK, VACUUM & REFILL GAS	New	100.00	0.00
6	RUSTPROOFING	New	80.00	60.00
Gross Labour Cost (\$\$)			4,080.00	2,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >