



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 1839E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT LH CORNER PANEL	TO REPAIR SEE LABOUR	618.00	-
1	FRONT TOP PANEL INNER (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT TOP PANEL OUTER	MTG CRACKED	480.00	382.15
1	FRONT CENTER PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	FUSO EMBLEM	NOT NECESSARY	120.00	-
1	FRONT GRILLE	SERVICEABLE	1,185.00	-
1	HEADLAMP LH	MTG CRACKED	980.00	555.00
1	HEADLAMP PANEL LOWER RUBBER LH	SERVICEABLE	650.00	-
1	HEADLAMP PANEL LH	TO REPAIR SEE LABOUR	295.00	-
1	SIGNAL LAMP LH	BROKEN	280.00	256.00
1	HEADLAMP SIDE COVER LH	SERVICEABLE	222.00	-
1	FRONT DOOR LH	BENT	2,140.00	1,750.00
1	FRONT DOOR LOWER HINGE LH	TO REPAIR SEE LABOUR	186.00	-
1	FRONT BUMPER CENTER	TO REPAIR SEE LABOUR	1,010.00	-
1	FRONT BUMPER LH SIDE	DENTED / CUT	480.00	334.00
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	220.00	-
1	FRONT STEP GARNISH LH	DENTED / CUT	718.00	409.00
	LESS 25% DISCOUNT		-2,396.00	-921.54
			7,188.00	2,764.61
<u>LABOUR</u>				
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT LH CORNER PANEL, FRONT TOP PANEL INNER, FRONT CENTER PANEL, HEADLAMP PANEL LH, FRONT DOOR LOWER HINGE LH, FRONT BUMPER CENTER AND FRONT BUMPER BRACKET LH.		1,200.00	450.00
	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		1,200.00	550.00
	TRANSFER DOOR PARTS TO ANOTHER DOOR.		120.00	60.00

Report Ref No. CS/SMR21006613/Kvf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DO ANTI RUST.		90.00	30.00
	CHECK WIRING SYSTEM, REPLACE FOCUS HEADLAMPS.		120.00	20.00
			2,730.00	1,110.00
GRAND TOTAL			9,918.00	3,874.61
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS/SMR21006613/Kvf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.