

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006620/ATCE2**Date:** 14/09/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00048312000

Claimant Vehicle No : SMS4843D **Insured Vehicle No :** GBJ5507X

Date of Loss: 05/06/2021 Nature of Claim: TP Claim No: SNM21D203261/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS4843D**

Make & Model: HYUNDAI AD AVANTE, 1.6 GLS S (A) Engine No: G4FGKU016729

Reg. Date: 28/02/2020 (Man. Year: 2019) Chassis No: KMHD841CMLU030609

Colour: Silver Odometer: 29227 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm

Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,355.12	12,259.84	12,095.28	49.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,480.00	2,730.00	2,750.00	50.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	29,835.12	14,989.84	14,845.28	49.76
Approved Total (Overridden) (\$\$)		12,000.00		
(\$\$)	29,835.12	12,000.00	17,835.12	59.78
+ GST 7.00/7.00% (\$\$)	2,088.46	840.00	1,248.46	59.78
Nett Amount (\$\$)	31,923.58	12,840.00	19,083.58	59.78

INSPECTION

Date of Assignment: 20/07/2021

Date Inspected: 11/06/2021 Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2021)
Parts:	143	HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS4843D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Distorted	1,895.00 FL	*1,782.00 FL
2	1		*BOOT LID BADGE WITH SWITCH	Damaged	356.00 FL	*356.00 FL
3	1		*BOOTLID EMBLEM (AVANTE)	Necessary	98.70 FL	*98.70 FL
4	1		*BOOT LID EMBLEM (S)	Necessary	56.00 FL	*56.00 FL
5	1		*BOOTLID SROILER	Cracked	896.00 FL	*485.00 FL
6	1		*BOOT LID REVERSE CAMERA	Damaged	926.10 FL	*582.00 FL
7	2		*BOOT LID LAMP	Cut	1,388.40 FL	*1,328.00 FL
8	2		*BOOT LID STOPPER	Not Necessary	60.00 FL	*- FL
9	1		*BOOT LID INNER LOCK	Damaged	296.20 FL	*296.20 FL
10	1		*BOOT LID LOCK CATCH	Not Necessary	43.70 FL	*- FL
11	1		*BOOT LID WEATHERSTRIP	Cut	254.00 FL	*254.00 FL
12	1		*BOOT LID INNER TRIM	Deformed	348.20 FL	*348.20 FL
13	2		*BOOT LID HINGE	Bent	228.40 FL	*228.40 FL
14	1		*SMART ENTRY ANTENNA	Cracked	320.00 FL	*186.00 FL
15	1		*REAR BUMPER	Distorted	654.00 FL	*654.00 FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	195.40 FL	*195.40 FL
17	5		*REAR BUMPER BRACKET	Damaged	200.00 FL	*90.00 FL
18	2		*REAR BUMPER REFLECTOR	Cracked	1,378.00 FL	*402.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Distorted	394.80 FL	*394.80 FL
20	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	394.20 FL	*394.20 FL
21	1		*REAR BUMPER UNDER COVER	Deformed	158.60 FL	*158.60 FL
22	1		*REAR BUMPER LOWER DIFFUSER	Distorted	453.10 FL	*453.10 FL
23	2		*TAILLAMP	Cracked	2,104.20 FL	*2,104.20 FL
24	2		*TAILLAMP SIDE GARNISH	Missing	136.00 FL	*136.00 FL
25	2		*TAILLAMP PANEL	Buckled	978.00 FL	*386.00 FL
26	1		*REAR WINDSCREEN	Not Necessary	845.00 FL	*- FL
27	1		*REAR WINDSCREEN MOULDING	Not Necessary	124.20 FL	*- FL
28	2		*REAR FENDER	Repair	3,784.00 FL	*- FL
29	2		*REAR FENDER INNER TRIM	Deformed	974.00 FL	*510.00 FL
30	2		*REAR FENDER COWLING	Not Necessary	354.00 FL	*- FL
31	1		*REAR END PANEL	Distorted	545.60 FL	*545.60 FL
32	1		*REAR END PANEL TOP GARNISH	Deformed	169.80 FL	*169.80 FL
33	1		*REAR FLOOR PANEL	Repair	740.80 FL	*- FL
34	1		*REAR FLOOR PANEL TOP BOARD	Deformed	319.10 FL	*319.10 FL
35	1		*REAR TOOLS BOX SPONGE	Cracked	412.00 FL	*285.00 FL
36	1		*REAR SPARE TYRE WHEEL NUT	Damaged	96.60 FL	*45.00 FL
37	1		*REAR CHASSIS FRAME MEMBER LH	Repair	545.00 FL	*- FL
38	2		*REAR AIR VENT	Not Necessary	244.60 FL	*- FL
39	2		*REAR NO PLATE GARNISH	Deformed	290.00 FL	*145.00 FL
40	1		*REAR WIRE HARNESH	Snapped	874.50 FL	*381.00 FL
41	1		*REAR EXHAUST SILENCER	Bent	854.00 FL	*688.00 FL
42	2		*REAR EXHAUST MOUNTING	Not Necessary	90.00 FL	*- FL
43	1		*REAR EXHAUST GASKET	Necessary	50.00 FL	*30.00 FL
44	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	177.00 FL	*- FL
45	1		*REAR DOOR LH	Not Necessary	1,878.30 FL	*- FL
46	2		*REAR DOOR BLACK STICKER LH	Not Necessary	90.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR DOOR OUTER MOULDING LH	Not Necessary	177.80 FL	*- FL
48	1		*REAR DOOR INNER LOCK LH	Not Necessary	394.70 FL	*- FL
49	1		*REAR DOOR LOCK CATCH LH	Not Necessary	64.40 FL	*- FL
50	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	198.00 FL	*- FL
51	1		*REAR NUMBER PLATE	Missing	80.00 FS	*50.00 FS
52	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
53	1		*REAR BUMPER LOWER LIP CLIP	Necessary	20.00 FS	*20.00 FS
54	1		*BOOT LID SEALANT	Necessary	80.00 FS	*20.00 FS
55	1		*BOOT LID INSULATOR CLIP	Necessary	50.00 FS	*20.00 FS
56	1		*TAILLAMP CLIP	Not Necessary	30.00 FS	*- FS
57	1		*TAILLAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
58	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
59	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
60	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
61	1		*REAR FENDER INNER COWLING CLIP	Not Necessary	100.00 FS	*- FS
62	1		*REAR FENDER INNER TRIM CLIP	Necessary	100.00 FS	*60.00 FS
63	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
64	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*60.00 FS
65	1		*REAR FLOOR PANEL INSULATION SEAL	Necessary	250.00 FS	*200.00 FS
66	1		*REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,056.40	15,157.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,701.28	2,897.46
Total Parts (\$\$)	24,355.12	12,259.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,800.00	1,200.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,200.00
3	TO APPLY TUFF COAT	New	180.00	60.00
4	PERFORM REAR WIRING CHECK	New	100.00	30.00
5	REMOVE & REFIX REAR DOOR PART	New	200.00	0.00
6	REMOVE AND INSTALL FUEL TANK AND FUEL PIPING TO ENABLE REPAIRS	New	300.00	0.00
7	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	400.00	80.00
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	200.00	50.00
9	REMOVE AND REFIX REVERSE CAMERA	New	250.00	50.00
10	TRANFER BOOT LID MECHANISM	New	150.00	60.00
11	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
Gross Labour Cost (\$\$)			5,480.00	2,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >