

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21006623/T1QF3N2**Date:** 23/09/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070115988
Claimant Vehicle No :	GBB2876S	Insured Vehicle No :	YP3870E
Date of Loss:	08/06/2021	Nature of Claim:	TP
		Claim No:	6455449283SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB2876S		
Make & Model:	NISSAN CABSTAR, 3.0 (M)	Engine No:	ZD30206552K
Reg. Date:	04/11/2008 (Man. Year: 2008)	Chassis No:	JN1SC2F24Z0800670
Colour:	Silver	Odometer:	317948 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	165R13(D)
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6/6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,501.00	1,350.90	150.10	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,030.00	900.00	46.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,431.00	2,380.90	1,050.10	30.61
Approved Total (Overridden) (S\$)		1,900.00		
Nett Amount (S\$)	3,431.00	1,900.00	1,531.00	44.62

INSPECTION

Date of Assignment:	11/06/2021	
Date Inspected:	16/06/2021	Inspected At: 3b Express Auto Pte Ltd (HQ) 25 Kaki Bukit Road, #06-77 Synergy @KB Singapore 417800
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT SIDE DECK PANEL	Bent	720.00 F	*720.00 FL
2	1		*AIR-CON CONDENSER	Bent	495.00 F	*495.00 FL
3	1		*AIR-CON FAN WITH MOTOR	Cracked	198.00 F	*198.00 FL
4	1		*AIR-CON FAN HOUSING	Cracked	88.00 F	*88.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$)					1,501.00	1,501.00
- List Item Discount on L Items 0.00/10.00% (\$)					0.00	150.10
Total Parts (\$)					1,501.00	1,350.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE,REPLACE/CUT,WELD KNOCK OUT DENTS TO STRAIGHTEN AREAS AFFECTED BY IMPACTED AS MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	950.00	600.00
2	PUTTY & SPRAY PAINTING TO ADJUSTED PANELS.JOB ALLOWANCE PANEL/MATERIALS	New	500.00	400.00
3	APPLY RUST PROOFING ON ADJUSTED PANELS	New	80.00	30.00
4	REMOVE AND REBUILD LABOUR	New	400.00	0.00
Gross Labour Cost (\$)			1,930.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >