



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2106243

INV Date 07/09/2021

Reference CC4/LPC21006630/Ags3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBA 8004H
Insured Veh. GBC 1224A
Claim No. 20/21/21/VC05/024642
Policy No. Z20VC05005655
Accident Date 10/06/2021
Inspection Date 11/06/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21006630/Ags3q2 Date: 07/09/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 1224A	Veh. Inspected	GBA 8004H	
Policy No.	Z20VC05005655	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024642	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	11/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN CABSTAR	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JN1SC2F24Z0859684	Colour	WHITE	
Odometer	158257 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	CONDOR	6 mm	
L/H Front Tyre	195 R15	CONDOR	6 mm	
R/H Rear Tyre	195 R15	CONDOR	6 mm	
L/H Rear Tyre	195 R15	CONDOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/06/2021	Inspection Date	11/06/2021	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 8004H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAIL-GATE (N)	DENTED	1,450.00	1,450.00
1	REAR TAIL-GATE NISSAN EMBLEM (N)	NECESSARY	106.50	106.50
2	REAR TAIL-GATE O/S & N/S LOCK (N)	NOT NECESSARY	208.40	-
2	REAR TAIL-GATE O/S & N/S LOCK (LOWER) (N)	NOT NECESSARY	206.40	-
3	REAR TAIL-GATE HINGES PINS (N)	NOT NECESSARY	12.00	-
1	REAR TAIL-GATE LOWER PANEL (N)	TO REPAIR SEE LABOUR	796.70	-
2	REAR TAIL-GATE O/S & N/S RUBBER STOPPER (N)	NOT NECESSARY	52.00	-
2	REAR O/S & N/S TAIL-LAMP (N)	CRACKED	798.60	530.60
1	REAR VIEW MIRROR (N)	CRACKED	310.00	310.00
1	REAR REG NO.PLATE BRACKET (N)	BENT	108.40	108.40
2	FRONT O/S & N/S HEAD LAMP (N)	O/S CRACKED	906.80	453.40
1	FRONT BUMPER (N)	DEFORMED	698.20	698.20
1	FRONT GRILLE (N)	CRACKED	665.60	461.90
1	FRONT GRILLE EMBLEM (N)	NECESSARY	96.20	96.20
1	FRONT PANEL (N)	TO REPAIR SEE LABOUR	996.50	-
1	FRONT 'CABSTA' EMBLEM (N)	NECESSARY	91.20	91.20
	LESS 10% DISCOUNT		-750.35	-430.64
			6,753.15	3,875.76
<u>SPECIAL NETT ITEMS</u>				
1	REAR TAIL-GATE 13 PAX EMBLEM (SN)	NECESSARY	20.00	10.00
1	REAR TAIL-GATE 70KMPH EMBLEM (SN)	NECESSARY	20.00	20.00
2	REAR REG.NO.PLATE (SN)	BENT	45.00	30.00
1	RIVET (SN)	NECESSARY	20.00	20.00
8	FRONT GRILLE CLIPS (SN)	NECESSARY	24.00	24.00
1	FRONT REG NUMBER PLATE (SN)	DENTED	45.00	30.00
			174.00	134.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE REAR & FRONT PORTION ,STRAIGHTEN & WELDING .INCLUSIVE OF THE REPAIR OF REAR TAIL-GATE LOWER PANEL AND FRONT PANEL.		1,200.00	800.00
	TO SPRAY PAINTING.		1,000.00	700.00
	TO REMOVE AND REPLACE REAR TAIL GATE .	NOT NECESSARY	80.00	-
	TO REMOVE & REPLACE REAR SPARE WHEEL BRACKET .	NOT NECESSARY	80.00	-
	TO CHECK WIRING .		80.00	60.00
	TO RE-SEAL ANTI-RUST.		80.00	50.00
			2,520.00	1,610.00
GRAND TOTAL			9,447.15	5,619.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CC4/LPC21006630/Ags3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBA 8004H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBA 8004H

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

