

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21006632/UGA3Q2
Date: 13/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800097725
Claimant Vehicle No :	SMD4382X	Insured Vehicle No :	SKN8191A
Date of Loss:	11/06/2021	Nature of Claim:	TP
		Claim No:	6638100102SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD4382X	Engine No:	D4FDJH554002
Make & Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Chassis No:	KNAHU815VJ7210934
Reg. Date:	20/08/2018 (Man. Year: 2018)	Odometer:	252791 km
Colour:	Brown		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	DURATURN 6 mm	Rear Left Side:	DURATURN 6 mm
Front Right Side:	DURATURN 6 mm	Rear Right Side:	DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,349.70	2,904.30	1,445.40	33.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,590.00	850.00	740.00	46.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,939.70	3,754.30	2,185.40	36.79
Approved Total (Overridden) (S\$)		3,000.00		

(S\$)	5,939.70	3,000.00	2,939.70	49.49
+ GST 7.00/7.00% (S\$)	415.78	210.00	205.78	49.49
Nett Amount (S\$)	6,355.48	3,210.00	3,145.48	49.49
+ Car Rental (5.0 x S\$77.00/day) (S\$)		385.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,597.00		

INSPECTION

Date of Assignment: 11/06/2021

Date Inspected: 11/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	627.00 FL	*627.00 FL
2	8		*FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
3	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	24.00 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP O/S	Serviceable	186.00 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP TRIM O/S	Cut	118.00 FL	*118.00 FL
6	1		*FRONT BUMPER EMBLEM	Not Necessary	68.00 FL	*- FL
7	1		*O/S FRONT FENDER	Badly Dented	384.00 FL	*384.00 FL
8	1		*O/S HEADLAMP	Scratched	1,559.00 FL	*1,558.00 FL
9	1		*O/S FRONT KNUCKLE ARM	Not Necessary	311.00 FL	*- FL
10	1		*O/S FRONT SHOCK ABSORBER	Not Necessary	302.00 FL	*- FL
11	1		*O/S FRONT WHEEL BEARING	Not Necessary	214.00 FL	*- FL
12	1		*O/S FRONT TYRE	Serviceable	250.00 FS	*- FS
13	1		*O/S FRONT WHEEL RIM	Warped	650.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,733.00	3,177.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	383.30	272.70
Total Parts (\$\$)	4,349.70	2,904.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
2	TO REINSTALL OF FRONT BUMPER PARKING SENSOR	New	80.00	0.00
3	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS ,REMOVE AND RENEWAL OF THE NECESSARY PARTS ,TO PERFORM FINAL CHECKING AND TESTING	New	250.00	0.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	80.00	80.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	600.00	350.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED POTTION	New	500.00	400.00
Gross Labour Cost (S\$)			1,590.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >