

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006636/GTF3N2**Date:** 01/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00079052000

Claimant Vehicle No : FBL8374G **Insured Vehicle No :** GBD3104U

Date of Loss: 12/05/2021 Nature of Claim: TP Claim No: SNM21D203315/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBL8374G**

Make & Model: HONDA NC750XA, 745cc Engine No: RC88E5011356

Reg. Date: 27/03/2017 (Man. Year: 2017) Chassis No: JH2RC90A0HK102496

Colour: Red Odometer: 105689 km

Engine Capacity: 745 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70ZR17 Rear Tyre Size: 160/60ZR17

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,313.00	1,146.00	167.00	12.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,170.00	470.00	700.00	59.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,483.00	1,616.00	867.00	34.92
+ GST 7.00/7.00% (S\$)	173.81	113.12	60.69	34.92
Nett Amount (S\$)	2,656.81	1,729.12	927.69	34.92

INSPECTION

Date of Assignment: 11/06/2021

Date Inspected: 17/06/2021 Inspected At: Boon Siew Singapore Pte Ltd - Ubi (HQ)
370 Ubi Road 3
Singapore 408651

Estimated Period of Repair: 1.0 days

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Dec 2021)	
Parts:	N/A	HONDA NC750XA 745cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL8374G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*UNIT,TAIL LIGHT	Cracked	186.30 FS	*186.30 FS
2	1		*LIGHT ASSY LICENS	Cut	59.20 FS	*59.20 FS
3	1		*FENDER A,RR	Cut	53.50 FS	*53.50 FS
4	1		*STAY,FENDER A	Deformed	70.00 FS	*70.00 FS
5	1		*FENDER B,RR	Deformed	167.90 FS	*167.90 FS
6	1		*COWL SET ILLUSTR *TYPE 1*	Deformed	56.00 FS	*56.00 FS
7	1		*COWL,L SEA *R305C*	Deformed	171.40 FS	*171.40 FS
8	1		*GRIP L,RR *NH303M*	Broken	154.70 FS	*154.70 FS
9	2		*BODY,CLIP	Necessary	5.00 FS	*5.00 FS
10	2		*CLIP TRIM	Necessary	4.00 FS	*4.00 FS
11	1		*RR NUMBER PLATE	Scratched	25.00 FS	*25.00 FS
12	1		*KAPPA TOP BOX,47L	Cracked	193.00 FS	*193.00 FS
13	1		*TOP BOX RACK	Repair	167.00 FS	*- FS
					Total Parts (\$\$)	1,313.00 1,146.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL DAMAGED PARTS,NECESSARY ATTACHMENT,REALIGN AFFECTED PORTION TO ALIGNMENT	New	1,050.00	350.00
2	USING HONDA MOTORCYCLE COMMUNICATION SYSTEM (MCS) TO ERASE/RESET MEMORY	New	120.00	120.00
Gross Labour Cost (\$\$)			1,170.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >