

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006637/ETCN2**Date:** 12/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00066482001

Claimant Vehicle No : YM2063R **Insured Vehicle No :** GBG4188E

Date of Loss: 03/06/2021 Nature of Claim: TP Claim No: SNM21D203314/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YM2063R**

Make & Model: MITSUBISHI FM657MSRDEC, 7.5 D (M) Engine No: 6D16982193

Reg. Date: 29/12/2005 (Man. Year: 2005) Chassis No: FM657MB10014

Colour: White Odometer: 637508 km

Engine Capacity: 7545 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5 Rear Tyre Size: 295/80R22.5

Front Left Side: HILO 4 mm Rear Left Side: HILO 4 mm

Front Right Side: HILO 4 mm Rear Right Side: HILO 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,642.08	6,200.35	2,441.73	28.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,000.00	1,000.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,642.08	7,200.35	3,441.73	32.34
Approved Total (Overridden) (\$\$)		5,750.00		
Nett Amount (\$\$)	10,642.08	5,750.00	4,892.08	45.97

INSPECTION

Date of Assignment: 06/10/2021

Date Inspected: 14/06/2021 Inspected At: 8 JOO KOON ROAD SINGAPORE 628972 BIGFOOT (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Oct 2021)	
Parts:	N/A	MITSUBISHI FM657MSRDEC 7.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YM2063R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT DOOR ASSY	Dented	4,866.64 FL	*4,866.64 FL
2	1		*FRONT BUMPER ASSY	Dented	1,063.57 FL	*1,063.57 FL
3	1		*FRONT RIGHT RIMS + TYRE	Not Necessary	1,966.83 FL	*- FL
4	1		*PROTECTOR FENDER	Broken	76.57 FL	*76.57 FL
5	1		*WELT MOLDING-RH	Broken	43.59 FL	*43.59 FL
6	1		*FENDER ASSY	Repair	718.42 FL	*- FL
7	1		*SIDE LAMP	Broken	79.77 FL	*79.77 FL
8	1		*LAMP,FR COMB	Broken	303.41 FL	*303.41 FL
9	1		*WALL STEPPER	Broken	233.51 FL	*233.51 FL
10	1		*SIDE CCTV CAMERA	Missing	225.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,577.31	6,867.06
- List Item Discount on L Items 10.00/10.00% (\$\$)	935.23	666.71
Total Parts (\$\$)	8,642.08	6,200.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE AND TO INSTALL OF PARTS INCLUDING KNOCKING,PUTTY	New	1,500.00	600.00
2	REPAINTING JOB	New	500.00	400.00
Gross Labour Cost (S\$)			2,000.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >