



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 1963E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET MOUNTS PDC SENSOR REAR (M)(SN)	NOT NECESSARY	61.00	-
1	RR BUMPER LH CORNER MOUNTING (SN)	NOT NECESSARY	143.35	-
1	REAR BUMPER LH MOUNT (M)(SN)	NOT NECESSARY	162.25	-
1	MOUNTING SMART OPENER (M)(SN)	NOT NECESSARY	45.75	-
1	REAR BUMPER PANEL PRIMED (M/PDC)(SN)	NOT NECESSARY	1,191.60	-
1	REAR BUMPER BOTTOM TRIM PANEL (M PD)(SN)	DENTED	297.90	297.90
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
10	EXPANDING RIVET WHITE (SN)(ADDITIONAL)	NECESSARY	19.50	19.50
			2,001.35	397.40
	<u>LABOUR</u>			
	TO REPLACE BUMPER REAR PANEL AND ATTACHMENTS.		1,275.00	850.00
	TO SPRAY PAINT BUMPER REAR PANEL.		1,038.00	986.00
	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	168.00
			2,490.00	2,004.00
	GRAND TOTAL		4,491.35	2,401.40
	RECOMMENDED COST OF REPAIRS			2,401.40

Report Ref No. CS/SMR21006639/Euf3n2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.