

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FV 9524J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SET BALANCER (CONSISTENT)	O/S CUT / N/S NOT NECESSARY	185.00	92.50
1	HANDLE BAR (CONSISTENT)	DISTORTED	185.00	185.00
1	SET MIRROR (CONSISTENT)	NOT NECESSARY	210.00	-
1	SET FORK TUBE (CONSISTENT)	BENT	1,200.00	1,200.00
1	FORK OIL SEAL (CONSISTENT)	NECESSARY	125.00	125.00
1	SET CRASH BAR (CONSISTENT)	CUT	280.00	280.00
1	REAR TAIL PANEL (CONSISTENT)	NOT NECESSARY	195.00	-
1	BLUE FLAME EXHAUST END CAN (CONSISTENT)	SERVICEABLE	1,600.00	-
1	STARTER SWITCH ASSY (CONSISTENT)	BROKEN	220.00	220.00
1	REAR MUDGUARD (CONSISTENT)	NOT NECESSARY	210.00	-
1	NUMBER PLATE REFLECTOR (CONSISTENT)	NOT NECESSARY	150.00	-
1	FRONT MUDGUARD (ADDITIONAL) (CONSISTENT)	BROKEN	220.00	220.00
1	SET HEAD LAMP ASSEMBLY (ADDITIONAL) (CONSISTENT)	CRACKED / DENTED	260.00	260.00
	LESS 10% DISCOUNT		-504.00	-258.25
			4,536.00	2,324.25
	<u>LABOUR</u>			
	TOWING FEE.	NOT NECESSARY	40.00	-
	REMOVE & REPLACE NECESSARY PARTS ,ALIGN & ETC.		200.00	150.00
	REMOVE & REPLACE FORK TUBE & TOP UP FORK OIL.		140.00	80.00
	DECAL BODY STICKER .	NOT NECESSARY	250.00	-
			630.00	230.00
	GRAND TOTAL		5,166.00	2,554.25

RECOMMENDED COST OF LUMP SUM REPAIRS		2,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM21006640/Dgs3q2



Automotive Assessor / Investigator