

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21006641/R1uce2
	8 SHENTON WAY SINGAPORE 0688		Date:	23/06/2021	
	ATTN: KHONG LYI	NN		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SJY 6887T	Veh. Inspected		SJR 2731Y
	Policy No.	GA549865	Coverage (\$)		0.00
	Claim No.	S1M03BIE	Excess (\$)		0.00
	Assign From	KHONG LYNN	Assign Date		11/06/2021
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA2 SEDAN 1.5L	c.c		1496
	Engine No.	HIDDEN	Year of Reg.		2016
	Chassis No.	MM6DL2SAAGW191587	Colour		BLACK
	Odometer	77003 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/60 R16	YOKOHAMA		6 mm
	L/H Front Tyre	195/60 R16	YOKOHAMA		6 mm
	R/H Rear Tyre	195/60 R16	YOKOHAMA		6 mm
	L/H Rear Tyre	195/60 R16	YOKOHAMA		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
5.	General Information				
	Accident Date	04/06/2021	Inspect Date /	Time	14/06/2021 (11:35 AM)
	Survey held at	D MOTORWERKZ PTE LTD			
	280 WOODLANDS INDUSTRIAL PARK E5 #01-03 SINGAPORE 757322				
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				

Report Ref No. CS3/ASM21006641/R1uce2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser