

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006643/KPA3Q2**Date:** 20/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070123633
Claimant Vehicle No :	GBF9435P	Insured Vehicle No :	GBC2246E
Date of Loss:	08/06/2021	Nature of Claim:	TP
		Claim No:	0962957108SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF9435P		
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Engine No:	1KD2621423
Reg. Date:	20/04/2017 (Man. Year: 2016)	Chassis No:	KDY2318025312
Colour:	White/Blue	Odometer:	172321 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Double Star 8 mm	Rear Left Side:	Bridgestone 2/2 mm
Front Right Side:	Double Star 8 mm	Rear Right Side:	Bridgestone 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	44,532.85	12,506.47	32,026.38	71.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,350.00	5,190.00	3,160.00	37.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,882.85	17,696.47	35,186.38	66.54
Approved Total (Overridden) (S\$)		14,150.00		
(S\$)	52,882.85	14,150.00	38,732.85	73.24
+ GST 7.00/7.00% (S\$)	3,701.80	990.50	2,711.30	73.24
Nett Amount (S\$)	56,584.65	15,140.50	41,444.15	73.24
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	11/06/2021	
Date Inspected:	11/06/2021 Inspected At:	Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	20.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRAKE AIR TANK	*Check	380.15 F	*- FL
2	1		*ENGINE MOUNTING	*Check	585.00 F	*- FL
3	1		*BRAKE OIL	*Check	40.00 F	*- FL
4	1		*CABIN STICKER -LH	Necessary	350.00 F	*350.00 FL
5	1		*FOG LAMP -LH	Serviceable	195.05 F	*- FL
6	1		*FOG LAMP -RH	Broken	915.05 F	*915.05 FL
7	1		*FOG LAMP BRACKET -LH	Repair	85.60 F	*- FL
8	1		*FOG LAMP BRACKET -RH	Bent	85.60 F	*85.60 FL
9	1		*FRONT BUMPER	Bent	572.80 F	*572.80 FL
10	1		*FRONT BUMPER FOG LAMP GARNISH -LH	Serviceable	85.00 F	*- FL
11	1		*FRONT BUMPER FOG LAMP GARNISH -RH	Missing	85.00 F	*85.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	342.80 F	*342.80 FL
13	1		*FRONT CORNER FENDER -LH	Serviceable	223.90 F	*- FL
14	1		*FRONT CORNER FENDER -RH	Serviceable	223.90 F	*- FL
15	1		*FRONT CROSS MEMBER	*Check	750.00 F	*- FL
16	1		*FRONT DOOR -LH	Bent	1,268.50 F	*1,268.50 FL
17	1		*FRONT DOOR -RH	Necessary	1,268.50 F	*1,268.50 FL
18	1		*FRONT DOOR HINGE BOTTOM -LH	Repair	82.50 F	*- FL
19	1		*FRONT DOOR HINGE BOTTOM -RH	Bent	82.50 F	*82.50 FL
20	1		*FRONT DOOR HINGE TOP -LH	Repair	82.50 F	*- FL
21	1		*FRONT DOOR HINGE TOP -RH	Repair	82.50 F	*- FL
22	1		*FRONT DOOR INNER TRIM -LH	Serviceable	420.00 F	*- FL
23	1		*FRONT DOOR INNER TRIM -RH	*Check	420.00 F	*- FL
24	1		*FRONT DOOR LOCK -LH	Repair	320.00 F	*- FL
25	1		*FRONT DOOR LOCK -RH	Repair	320.00 F	*- FL
26	1		*FRONT DOOR MOTOR -LH (REGULATOR)	Serviceable	350.00 F	*- FL
27	1		*FRONT DOOR MOTOR -RH (REGULATOR)	Jammed	350.00 F	*350.00 FL
28	1		*FRONT DOOR OUTER HANDLE -LH	Dented	250.15 F	*250.15 FL
29	1		*FRONT DOOR OUTER MOULDING -LH	Distorted	145.00 F	*145.00 FL
30	1		*FRONT DOOR OUTER MOULDING -RH	Serviceable	145.00 F	*- FL
31	1		*FRONT DOOR PILLAR -LH	Repair	780.15 F	*- FL
32	1		*FRONT DOOR PILLAR -RH	Repair	780.15 F	*- FL
33	1		*FRONT DOOR REGULATOR -LH	Serviceable	280.00 F	*- FL
34	1		*FRONT DOOR REGULATOR -RH	Bent	280.00 F	*280.00 FL
35	1		*FRONT DOOR SIDE COVER -LH	Cut	85.60 F	*85.60 FL
36	1		*FRONT DOOR INNER GLASS SIDE MIRROR -RH	No such part	315.00 F	*- FL
37	1		*FRONT DOOR INNER GLASS SIDE MIRROR -LH	*Check	75.85 F	*- FL
38	1		*FRONT DOOR SIDE RUBBER -RH	*Check	75.85 F	*- FL
39	1		*FRONT DOOR STICKER -LH	Necessary	25.00 F	*25.00 FL
40	1		*FRONT DOOR STICKER -RH	Necessary	25.00 F	*25.00 FL
41	1		*FRONT DOOR WEATHERSTRIP -LH	*Check	125.60 F	*- FL
42	1		*FRONT DOOR WEATHERSTRIP -RH	*Check	125.60 F	*- FL
43	1		*FRONT FENDER -LH	Bent	195.00 F	*195.00 FL
44	1		*FRONT FENDER -RH	Repair	195.00 F	*- FL
45	1		*FRONT GRILLE	Missing	434.20 F	*434.20 FL
46	1		*FRONT GRILLE CLIPS	Necessary	30.00 F	*30.00 FL
47	1		*FRONT GRILLE LOGO	Missing	95.15 F	*95.15 FL
48	1		*FRONT HEADLAMP -LH	Cut	858.40 F	*858.40 FL
49	1		*FRONT HEADLAMP -RH	Broken	858.40 F	*858.40 FL
50	1		*FRONT KNUCKLE ARM -LH	*Check	641.70 F	*- FL
51	1		*FRONT KNUCKLE ARM -RH	*Check	641.70 F	*- FL
52	1		*FRONT LOWER ARM -LH	*Check	320.00 F	*- FL
53	1		*FRONT LOWER ARM -RH	*Check	320.00 F	*- FL
54	1		*FRONT PANEL	Bent	385.00 F	*385.00 FL
55	1		*FRONT PANEL CENTRE GARNISH	Bent	185.60 F	*185.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT PANEL SIDE GARNISH -LH	Serviceable	85.60 F	*- FL
57	1		*FRONT PANEL SIDE GARNISH -RH	Distorted	85.60 F	*85.60 FL
58	1		*FRONT SHOCK ABSORBER -LH	*Check	285.90 F	*- FL
59	1		*FRONT SHOCK ABSORBER -RH	*Check	285.90 F	*- FL
60	1		*FRONT SIDE MIRROR -LH	Cut	315.00 F	*315.00 FL
61	1		*FRONT SIDE MIRROR GARNISH-LH	Repeated	135.15 F	*- FL
62	1		*FRONT STEERING BOX	Cracked	880.15 F	*880.15 FL
63	1		*FRONT STEERING RACK	*Check	2,800.00 F	*- FL
64	1		*FRONT STEP GARNISH -LH	Cut	185.00 F	*185.00 FL
65	1		*FRONT STEP GARNISH -RH	Broken	185.00 F	*185.00 FL
66	1		*FRONT STEP INNER PANEL -RH	Repair	265.00 F	*- FL
67	1		*FRONT UPPER ARM -LH	*Check	475.20 F	*- FL
68	1		*FRONT UPPER ARM -RH	*Check	475.20 F	*- FL
69	1		*FRONT WHEEL BEARING -LH	*Check	375.20 F	*- FL
70	1		*FRONT WHEEL BEARING -RH	*Check	375.20 F	*- FL
71	1		*FRONT WHEEL RIM CAP -LH	Serviceable	100.00 F	*- FL
72	1		*FRONT WINDSCREEN	Cracked	650.00 F	*650.00 FL
73	1		*FRONT WINDSCREEN GLASS MOULDING	Not Necessary	108.50 F	*- FL
74	1		*FRONT WIPER ARM -LH	Serviceable	90.05 F	*- FL
75	1		*FRONT WIPER ARM -RH	Serviceable	90.05 F	*- FL
76	1		*FRONT WIPER BLADE -LH	Serviceable	30.00 F	*- FL
77	1		*FRONT WIPER BLADE -RH	Serviceable	30.00 F	*- FL
78	1		*FRONT WIPER PANEL	Bent	285.10 F	*285.10 FL
79	1		*FUSE BOX	*Check	280.15 F	*- FL
80	1		*FUSE BOX BRACKET	*Check	135.15 F	*- FL
81	1		*HEADLAMP LOWER RUBBER -LH	Missing	40.00 F	*40.00 FL
82	1		*HEADLAMP LOWER RUBBER -RH	Missing	40.00 F	*40.00 FL
83	1		*REAR CANOPY (LOCAL REPAIR)	Dented	1,200.00 FS	*350.00 FS
84	1		*SET REAR CARGO SIDE DOOR HINGE	Dented	250.00 F	*250.00 FL
85	1		*REAR CARGO SIDE STOPPER RUBBER -LH (FRONT)	*Check	40.00 F	*- FL
86	1		*REAR CARGO SIDE STOPPER RUBBER -LH (REAR)	*Check	40.00 F	*- FL
87	1		*REAR DOOR PILLAR -LH	Bent	780.15 F	*780.15 FL
88	1		*REAR TAILLAMP -LH	Serviceable	285.00 F	*- FL
89	1		*REAR TYRE FENDER -LH (FRONT)	Repair	180.00 F	*- FL
90	1		*REAR TYRE FENDER -LH (REAR)	Repair	180.00 F	*- FL
91	1		*STABILIZER BAR CENTRE	*Check	480.15 F	*- FL
92	1		*STEERING BOX BALL JOINT	*Check	280.15 F	*- FL
93	1		*WIPER LINK	Serviceable	215.20 F	*- FL
94	1		*WIPER MOTOR	Serviceable	445.10 F	*- FL
95	1		*FRONT DOOR SIGNAL LAMP -LH	Broken	165.15 F	*165.15 FL
96	1		*FRONT DOOR SIGNAL LAMP -RH	Broken	165.15 F	*165.15 FL
97	1		*REAR AXLE SUP -LH	*Check	2,200.00 F	*- FL
98	1		*REAR AXLE SUP -RH	Repeated	2,200.00 F	*- FL
99	1		*REAR WHEEL BEARING -LH	*Check	250.00 F	*- FL
100	1		*REAR WHEEL BEARING -RH	*Check	250.00 F	*- FL
101	1		*FRONT MUDFLAP -LH	Dented / Cut	380.15 F	*380.15 FL
102	1		*BODY STICKER	*Check	1,200.00 F	*- FL
103	1		*AIRCON BLOWER COVER	*Check	684.15 F	*- FL
104	1		*REAR CARGO SAFETY GATE -LH	Bent	520.00 F	*520.00 FL
105	1		*REAR CARGO SAFETY GATE -RH	Repair	520.00 F	*- FL
106	1		*REAR CARGO SIDE DOOR -LH	Bent	850.15 F	*850.15 FL
107	1		*REAR CARGO SIDE DOOR -RH	Repair	850.15 F	*- FL
108	1		*FRONT NUMBER PLATE	Dented	50.00 FS	*40.00 FS
109	1		*FRONT TYRE -LH	*Check	280.00 FS	*- FS
110	1		*FRONT TYRE -RH	Serviceable	280.00 FS	*- FS
111	1		*FRONT WHEEL RIM -LH	Dented	380.00 FS	*380.00 FS
112	1		*FRONT WHEEL RIM -RH	Serviceable	380.00 FS	*- FS
113	1		*FRONT WINDSCREEN RUBBER (50%)	Necessary	198.15 FS	*99.08 FS
114	1		*REAR WHEEL RIM-LH (OUTSIDE)	Dented	200.00 FS	*200.00 FS
115	1		*REAR WHEEL RIM-RH (OUTSIDE)	Dented	200.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
116	1		*REAR TYRE -LH (OUTSIDE)	*Check	100.00 FS	*- FS
117	1		*REAR TYRE -RH (OUTSIDE)	*Check	100.00 FS	*- FS
118	1		*FRONT WINDSCREEN IU BRACKET	Necessary	25.00 FS	*25.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$)	44,532.85	16,243.93
				- List Item Discount on L Items 0.00/25.00% (\$)	0.00	3,737.46
				Total Parts (\$)	44,532.85	12,506.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & RELACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	3,000.00	2,400.00
2	TO PUTTY ,APPLY PRIMER & SPRAY -PAINT ON THE AFFECTED PORTION	New	3,000.00	1,800.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	350.00	180.00
4	TO REMOVE /REPLACE FRONT UNDERCARRIAGE LABOUR	New	600.00	240.00
5	TO REMOVE /REFIT FRONT WINDSCREEN TO FACILITATE REPAIRS	New	200.00	60.00
6	LABOUR TO REMOVE AND REPLACE FRONT DOOR COMPONENTS	New	200.00	120.00
7	LABOUR TO REMOVE AND REPLACE FRONT DASHBOARD	New	600.00	250.00
8	TO TOW VEHICLE TO WORKSHOP (*Check)	New	180.00	0.00
9	WHEEL ALIGNMENT	New	120.00	100.00
10	TO CHECK WIRING FUNCTIONS	New	100.00	40.00
Gross Labour Cost (\$\$)			8,350.00	5,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >