

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21006644/UBA3Q2
Date: 14/07/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0000326_01		
Claimant Vehicle No :	SJK2761Y	Insured Vehicle No :	SMT4152J		
Date of Loss:	11/06/2021	Nature of Claim:	TP	Claim No:	MFL2021D0002540

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK2761Y		
Make & Model:	HONDA FIT, 1.3 G (A)	Engine No:	L13A4098001
Reg. Date:	14/10/2008 (Man. Year: 2008)	Chassis No:	GE61087423
Colour:	Blue	Odometer:	264931 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,123.60	1,376.48	1,747.12	55.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	880.00	1,100.00	55.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,103.60	2,256.48	2,847.12	55.79
Approved Total (Overridden) (S\$)		1,800.00		

Nett Amount (S\$)	5,103.60	1,800.00	3,303.60	64.73
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,107.45		
Global Sum Settlement (S\$)		2,060.00		

INSPECTION

Date of Assignment: 14/06/2021

Date Inspected: 14/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2021)
Parts: 144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJK2761Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S FENDER	Repair	460.80 FL	*- FL
2	1		*FRONT O/S FENDER INNER SHIELD	Not Necessary	87.40 FL	*- FL
3	8		*FRONT O/S FENDER INNER SHIELD CLIPS	Not Necessary	32.00 FL	*- FL
4	1		*O/S HEAD LAMP ASSY	Cracked	703.50 FL	*703.50 FL
5	1		*O/S HEAD LAMP LOWER BRACKET	Not Necessary	29.50 FL	*- FL
6	1		*FRONT SUPPORT PANEL	Not Necessary	434.80 FL	*- FL
7	1		*FRONT O/S WHEEL HOUSE LOWER PANEL	Repair	283.00 FL	*- FL
8	1		*FRONT BUMPER	Cut	614.00 FL	*566.20 FL
9	10		*FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
10	1		*FRONT BUMPER O/S SIDE RETAINER	Bent	28.40 FL	*28.40 FL
11	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	271.10 FL	*- FL
12	1		*FRONT BUMPER O/S SIDE BRACKET CLIPS	Necessary	7.50 FL	*7.50 FL
13	1		*FRONT O/S SPORT RIM	Cut	450.00 FS	*300.00 FS
14	1		*FRONT O/S WHEEL TYRE	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,722.00	1,645.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	598.40	269.12
Total Parts (\$\$)	3,123.60	1,376.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT	New	50.00	20.00
2	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING	New	120.00	60.00
3	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	60.00	0.00
4	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK,STRAIGHTEN & KNOCKING OUT NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	800.00	300.00
5	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	950.00	500.00
			Gross Labour Cost (S\$)	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >