



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV14095/ TASK COMM ENGINEERING PTE LTD Reg No/Reg Date SMZ5052B / 29/04/202 Date In/Mileage 11/06/2021/ 0 Chassis No KNAF3416MM5100900 Engine No G4FGLH711927 Make/Model KIA/CERATO 1.6 A EX G730 Colour/Trim 4SS / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	14/06/2021/ 08:20	QUK	289 / Patrick Lee	34559		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, FRT LH FENDER , SUPPORT, FRT LH DOOR & AFFECTED AR				2-5 X 490			1800.00
E PNT98000 PAINT WORK ON FRT BUMPER, FRT LH FENDER, FRT LH DOOR & BODY KIT				4 X 350			1400.00
M SUNDRY PERFORM RUST PREVENTION							40.00
E PNT88000 REMOVE & REPLACE BODY KIT							80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment							120.00
M SUNDRY TO TRANSFER FRT LH RIM INCLUDING BALANCING							30.00
E PNT88000 TO TRANSFER FRT LH DOOR ATTACHMENT TO NEW PANEL							150.00
M SUNDRY TO SUPPLY FRT LH SPORT RIM							380.00
M SUNDRY SUNDRIES							50.00
M NEW K3 BODYKIT				1.00	1721.00	00.00	1721.00
M LAMP ASSY-HEAD,LH				1.00	1219.00	20.00	975.20
M LAMP ASSY-HEAD,RH				1.00	1219.00	20.00	975.20
M STRUT ASSY-FR,LH				1.00	280.00	20.00	224.00
M INSULATOR ASSY-STRUT				1.00	85.00	20.00	68.00
M PAD-FRONT SPRING,UPR				1.00	11.00	20.00	8.80
M KNUCKLE-FRONT AXLE,LH				1.00	350.00	20.00	280.00
M HUB ASSY-FR WHEEL				1.00	436.00	20.00	348.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV14095/ TASK COMM ENGINEERING PTE LTD Reg No/Reg Date SMZ5052B / 29/04/202 Date In/Mileage 11/06/2021/ 0 Chassis No KNAF3416MM5100900 Engine No G4FGLH711927 Make/Model KIA/CERATO 1.6 A EX G730 Colour/Trim 4SS / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	14/06/2021/ 08:20	QUK	289 / Patrick Lee	34559

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GEAR ASSY-STEERING X N/A	1.00	770.00	20.00	616.00
M PANEL-FENDER, LH / 00 ? X N/A	1.00	430.00	20.00	344.00
M INSULATOR-FENDER LH X N/A	1.00	27.00	20.00	21.60
M PANEL ASSY-FRONT DOOR, LH / 00 ? X N/A	1.00	1277.00	20.00	1021.60
M CARRIER ASSY-FRONT END MODULE X N/A	1.00	675.00	20.00	540.00
M BEAM COMPLETE-FR BUMPER X N/A	1.00	497.00	20.00	397.60
M GUARD ASSY-FRONT WHEEL, LH / TN	1.00	95.00	20.00	76.00
M MOULDING ASSY-FRT DR FRAME, LH / REC	1.00	37.00	20.00	29.60
M W/STRIP ASSY-FR DR BELT O/S LH ? X N/A	1.00	64.00	20.00	51.20
M W/STRIP ASSY-FR DR SIDE LH ? X N/A	1.00	102.00	20.00	81.60
M COVER-FR BUMPER / BR ? X N/A	1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER / ? X N/A	1.00	262.00	20.00	209.60
M LAMP ASSY-FRONT FOG, LH / ? X N/A	1.00	303.00	20.00	242.40
M LAMP ASSY-SIDE REPEATER, LH / CAT	1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER, LH / BR	1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY / ? X N/A	1.00	84.00	20.00	67.20
M BRACKET-FR BUMPER UPR SIDE MTG / BR	1.00	22.00	20.00	17.60
M ORNAMENT-KIA NO.115 / REC	1.00	32.00	20.00	25.60
M BLACK TAPE-FR DR RR, LH / REC	1.00	13.00	20.00	10.40

* Side mirror LH / BR (no price)

Stere (LKK) 00-N/A AL
14/6/21, 11.00am Express -?
P/P
M Bel Sky
7 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Confirm & accepted by

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized by Repairer

7% GST on **Nett** 13185.00 **13,185.00**
922.95

Total Payable **14,107.95**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.