

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006646/ATCN2**Date:** 08/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00085712100

Claimant Vehicle No : SLK1224P **Insured Vehicle No :** SJG9452P

Date of Loss: 09/06/2021 Nature of Claim: TP Claim No: SNM21D203303/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK1224P**

Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UDS1186

Reg. Date: 06/01/2017 (Man. Year: 2016) Chassis No: MMBSTA13AHH004344

Colour: Grey Odometer: 46576 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,823.40	1,578.60	244.80	13.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	830.00	450.00	35.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,103.40	2,408.60	694.80	22.39
+ GST 7.00/7.00% (S\$)	217.24	168.60	48.64	22.39
Nett Amount (S\$)	3,320.64	2,577.20	743.44	22.39

INSPECTION

Date of Assignment: 14/06/2021

Date Inspected: 14/06/2021 Inspected At: KAI MOTOR TRADING (HQ)
BLK 3007 UBI ROAD 1, #01-440
Singapore 408701

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Sep 2021)
Parts: 143	mitsubishi ATTRAGE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK1224P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	666.00 FN	*666.00 FN
2	10		*FRONT BUMPER CLIPS	Necessary	60.00 FN	*30.00 FN
3	1		*FRONT BUMPER SIDE RETAINERS	O/s Damaged	34.00 FN	*17.00 FN
4	1		*FRONT FOG LAMP COVER RH	Not Necessary	127.00 FN	*- FN
5	1		*HEAD LAMP RH	Cracked	544.00 FN	*544.00 FN
6	1		*FRONT FENDER RH	Dented	438.00 FN	*438.00 FN
7	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	98.00 FN	*- FN
8	1		*FRONT FENDER CHROME GARNISH RH	Necessary	59.00 FN	*59.00 FN

F=Franchise part. N=NettItemDisc.

Sub Total (\$\$)	2,026.00	1,754.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	202.60	175.40
Total Parts (\$\$)	1,823.40	1,578.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	COMPUTER WHEEL ALIGNMENT	New	120.00	0.00
2	TO DISMANTLE & REPLACE DAMAGE PARTS,PANEL BEAT WHERE NECESSARY	New	450.00	400.00
3	TO PUTTY,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	550.00	400.00
4	TO REMOVE UPHOLSTERY	New	80.00	0.00
5	TO CHECK WIRING FUNCTIONS	New	80.00	30.00
			Gross Labour Cost (\$)	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >