



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4830D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	TO REPAIR SEE LABOUR	459.40	-
10	REAR BUMPER CLIPS	SERVICEABLE	22.00	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,768.30	-
1	REAR BUMPER SIDE BRACKET LH	SERVICEABLE	55.80	-
1	RR WHEEL HUB CAP LH	SCRATCHED	346.40	346.40
	LESS 20% DISCOUNT		-530.38	-69.28
			2,121.52	277.12
<u>NETT ITEMS</u>				
1	REAR FENDER PETROL STICKER (N)	NECESSARY	15.00	15.00
	LESS 10% DISCOUNT		-	-1.50
			15.00	13.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER COVER AND REAR FENDER LH.		700.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.		60.00	40.00
			1,360.00	1,240.00
GRAND TOTAL			3,546.52	1,580.62
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,580.62

Report Ref No. NS/INC21006647/Nvcn2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.