

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC21006652/Vvf3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	17/06/2021	
			Code:	LPC2	
1.		Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	GBB 6935D	Veh. Inspected	SKB 4960L	
	Policy No.	Z21VC05007341	Coverage (\$)	0.00	
	Claim No.	21/21/21/VC05/0024646	Excess (\$)	0.00	
	Assign From	KENNY LIM	Assign Date	14/06/2021	
2.	Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH 1.8X A	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2011	
	Chassis No.	ZGE200067868	Colour	BLUE	
	Odometer	153034 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	MICHELIN	6 mm	
	L/H Front Tyre	195/65 R15	MICHELIN	6 mm	
	R/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
	L/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA			
5.	General Information				
	Accident Date	09/06/2021	Inspect Date / Time	14/06/2021 ( 04:00 PM )	
	Survey held at RS AUTOMOTIVE WORKSHOP				
		BLK 3006 UBI ROAD 1 #01-394 SINGAPORE 408700			
5a.		Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC21006652/Vvf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser