

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006654/KPA3Q2
Date: 30/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210033916
Claimant Vehicle No :	SCV5225J	Insured Vehicle No :	SJQ3778L
Date of Loss:	10/06/2021	Nature of Claim:	TP
		Claim No:	5977083722SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCV5225J		
Make & Model:	MERCEDES-BENZ E250, 2.0 SEDAN (R18) (A)	Engine No:	27492030347587
Reg. Date:	08/05/2015 (Man. Year: 2014)	Chassis No:	WDD2120362B122957
Colour:	Metallic Grey	Odometer:	93165 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	265/35 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 4 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	41,292.75	31,082.00	10,210.75	24.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,115.00	4,070.00	6,045.00	59.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	51,407.75	35,152.00	16,255.75	31.62
Approved Total (Overridden) (S\$)		23,500.00		

Nett Amount (S\$)	51,407.75	23,500.00	27,907.75	54.29
+ Loss of Use (16.0 x S\$100.00/day) (S\$)		1,600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		25,107.45		

INSPECTION

Date of Assignment: 14/06/2021

Date Inspected: 14/06/2021

Estimated Period of Repair: 13.0 days

Inspected At:

Lim Yew Boo Spray Paint Co (HQ)
 Blk 10 Sin Ming Industrial Estate, #01-10
 Singapore 575645

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	2,989.00 FN	*2,645.00 FN
2	1		*FRONT BONNET SEAL (CENTRE)	Cracked	128.00 FN	*128.00 FN
3	1		*FRONT BONNET INSULATOR	Serviceable	215.00 FN	*- FN
4	10		*FRONT BONNET INSULATOR CLIPS	Necessary	45.00 FN	*45.00 FN
5	2		*FRONT BONNET HINGES	Repair	356.00 FN	*- FN
6	2		*FRONT BONNET SPRING	Serviceable	32.00 FN	*- FN
7	1		*FRONT BONNET EMBLEM	Dented	111.00 FN	*111.00 FN
8	2		*FRONT BONNET LOCK TOP LH & RH	Distorted	78.00 FN	*78.00 FN
9	2		*FRONT BONNET LOCK BOTTOM LH & RH	Distorted	82.00 FN	*82.00 FN
10	1		*FRONT BONNET LOCK CENTRE	Bent	98.00 FN	*98.00 FN
11	1		*FRONT BONNET LOCK SWITCH	Dented	49.00 FN	*49.00 FN
12	1		*FRONT BUMPER	Buckled	1,658.00 FN	*1,658.00 FN
13	1		*FRONT BUMPER GRILLE SUPPORT	Distorted	115.00 FN	*115.00 FN
14	2		*FRONT BUMPER SIDE RETAINER	Serviceable	192.00 FN	*- FN
15	1		*FRONT BUMPER REINFORCEMENT	Bent	648.00 FN	*648.00 FN
16	1		*FRONT BUMPER BEAM	Repair	300.00 FN	*- FN
17	1		*FRONT BUMPER LOWER GRILLE /CENTRE	Serviceable	88.00 FN	*- FN
18	2		*FRONT BUMPER LOWER GRILLE /SIDE	Serviceable	114.00 FN	*- FN
19	2		*FRONT BUMPER LOWER GRILLE CHROME/SIDE	Serviceable	240.00 FN	*- FN
20	1		*FRONT BUMPER TOWING HOOK COVER	Serviceable	61.00 FN	*- FN
21	2		*FRONT HEADLAMP ASSY	Mtg Cracked	11,756.00 FN	*11,040.00 FN
22	2		*FRONT HEADLAMP LOWER PANEL	Repair	626.00 FN	*- FN
23	1		*FRONT FENDER RH	Repair	1,214.00 FN	*- FN
24	1		*FRONT AIR CON CONDENSER	Bent	1,513.00 FN	*1,513.00 FN
25	1		*FRONT AIR CON HOSE	Serviceable	210.00 FN	*- FN
26	1		*FRONT INTAKE HOSE	Dented	258.00 FN	*258.00 FN
27	1		*FRONT RADIATOR	Bent	1,598.00 FN	*1,486.00 FN
28	1		*FRONT RADIATOR UPPER BRAFFLE	Cracked	49.00 FN	*49.00 FN
29	1		*FRONT RADIATOR FAN ASSY	Cracked	1,742.00 FN	*1,581.00 FN
30	1		*FRONT RADIATOR GRILLE CARRIER	Cracked	298.00 FN	*298.00 FN
31	1		*FRONT RADIATOR GRILLE BASE	Cracked	220.00 FN	*220.00 FN
32	1		*FRONT RADIATOR GRILLE TRIM/CHROME	Cracked	403.00 FN	*403.00 FN
33	1		*FRONT RADIATOR GRILLE COVER	Cracked	208.00 FN	*208.00 FN
34	4		*FRONT RADIATOR GRILLE MLDG	Bent	192.00 FN	*192.00 FN
35	1		*FRONT RADIATOR GRILLE STAR	Missing	155.00 FN	*155.00 FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT RADIATOR GRILLE STAR BASE	Missing	88.00 FN	*88.00 FN
37	1		*FRONT SUPPORT TOP PANEL /CENTRE	Buckled	185.00 FN	*185.00 FN
38	1		*FRONT SUPPORT TOP PANEL LH	Distorted	317.00 FN	*317.00 FN
39	1		*FRONT SUPPORT TOP PANEL RH	Buckled	317.00 FN	*317.00 FN
40	1		*FRONT SUPPORT TOP CENTRE GARNISH	Dented	153.00 FN	*153.00 FN
41	1		*FRONT SUPPORT BRACE PANEL	Bent	85.00 FN	*85.00 FN
42	4		*FRONT SENSOR	Serviceable	1,252.00 FN	*- FN
43	4		*FRONT SENSOR HOLDERS	Not Necessary	104.00 FN	*- FN
44	1		*FRONT SENSOR WIRE HARNESS	Serviceable	268.00 FN	*- FN
45	1		*ROOF PANEL SIDE MLDG	Serviceable	455.00 FN	*- FN
46	8		*ROOF PANEL SIDE MLDG CLIPS	Not Necessary	44.00 FN	*- FN
47	1		*REAR BOOT LID	Bent	3,312.00 FN	*3,312.00 FN
48	1		*REAR BOOT LID WEATHERSTRIP	Serviceable	217.00 FN	*- FN
49	1		*REAR BOOT LID STAY EMBLEM	Necessary	65.00 FN	*65.00 FN
50	3		*REAR BOOT LID STAY CLIPS	Necessary	6.00 FN	*6.00 FN
51	1		*REAR EMBLEM E250	Necessary	91.00 FN	*91.00 FN
52	1		*REAR EMBLEM 7G-TRONIC	Necessary	111.00 FN	*111.00 FN
53	1		*REAR LID OUTER HANDLE (CHROME)	Serviceable	134.00 FN	*- FN
54	5		*REAR LID OUTER HANDLE INSIDE CLIP	Not Necessary	17.50 FN	*- FN
55	1		*REAR BUMPER	Broken	1,859.00 FN	*1,721.00 FN
56	1		*REAR BUMPER RETAINER	O/S Cracked	78.00 FN	*39.00 FN
57	1		*REAR BUMPER BEAM	Bent	969.00 FN	*969.00 FN
58	1		*REAR BUMPER INSIDE PART	Cracked	297.00 FN	*297.00 FN
59	2		*REAR BUMPER BRACKET	Cracked	54.00 FN	*54.00 FN
60	2		*REAR BUMPER CHROME (SIDE)	Necessary	304.00 FN	*304.00 FN
61	1		*REAR BUMPER LOWER CHROME	Cracked	189.00 FN	*189.00 FN
62	4		*REAR REVERSE PDC SENSOR	Missing /Shorted (2 PCS ONLY)	1,252.00 FN	*626.00 FN
63	4		*REAR REVERSE PDC SENSOR HOLDER	Necessary (2 PCS ONLY)	104.00 FN	*52.00 FN
64	1		*REAR SILENCER OUTER CHROME FINISHER	Dented	285.00 FN	*285.00 FN
65	1		*REAR SILENCER OUTER CHROME FINISHER BRACKET	Repair	53.00 FN	*- FN
66	1		*REAR SILENCER HEAT SHIELD	Bent	102.00 FN	*102.00 FN
67	1		*REAR FENDER /RH	Repair	2,655.00 FN	*- FN
68	1		*REAR FENDER INNER SHIELD /RH	Serviceable	282.00 FN	*- FN
69	1		*REAR TAILLAMP /RH	Broken	864.00 FN	*864.00 FN
70	1		*REAR REFLECTOR /RH	Broken	538.00 FN	*538.00 FN
71	1		*FRONT NO PLATE (EMBOSS)	Dented	25.00 FS	*25.00 FS
72	1		*FRONT NO PLATE HOLDER	Serviceable	25.00 FS	*- FS
73	20		*FRONT BUMPER EXTENSION FASTENER	Necessary	140.00 FS	*140.00 FS
74	20		*FRONT BUMPER EXTENSION GROMMET SCREW	Necessary	160.00 FS	*160.00 FS
75	20		*FRONT BUMPER FASTENER	Necessary	160.00 FS	*160.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*RIVERTS 003 990 9497MB (30 PCS)	Necessary	150.00 FS	*150.00 FS
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (S\$)					45,807.50	34,465.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)					4,514.75	3,383.00
Total Parts (S\$)					41,292.75	31,082.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	MOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR JOB	New	400.00	0.00
2	TO RE-SET ABS SYSTEM & EARSE REGISTERED FAULT	New	180.00	0.00
3	TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION	New	55.00	20.00
4	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED FRT PANELS	New	120.00	60.00
5	LABOUR CHARGE FOR DISMANTLE & RENEW AIR-CON CONDENSER ,HOSE & AIR CON RELATED PARTS }	New	280.00	100.00
6	TO VACUM AND TOP UP GAS }	New	180.00	0.00
7	LABOUR TO CHECK AND REPLACE FRONT SENSOR	New	120.00	60.00
8	TO REPAIR ,PANEL BEAT ON AFFECTED AREA ,RE-STRAIGHTEN ON AFFECTED RIGHT FRT HOUSING ,CUT & WELD ON REPLACED PANEL & LABOUR TO REPLACE THE ABOVE FRONT PARTS	New	2,000.00	800.00
9	TO PUTTY ,PRIMER & SPRAY PAINT ON FRT BONNET ,FRT BUMPER,RIGHT & LEFT FRT FENDER ,LEFT & RIGHT AFFECTED ROOF TOP SIDE CHANNEL & FRONT SENSOR USING 2K PAINT	New	2,100.00	1,100.00
10	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED REAR PANEL	New	120.00	30.00
11	LABOUR TO REMOVE/REFIX REAR SEAT ,INTERIOR GARNISH ,ETC	New	220.00	80.00
12	LABOUR TO REMOVE & REFIX REAR WINDSCREEN IN ORDER TO FACILITATE REPAIR JOBS	New	150.00	0.00
13	LABOUR TO CHECK AND REPLACE REAR SENSOR	New	120.00	60.00
14	TO REMOVE ,REPAIR REAR EXHAUST SILENCER & REPLACE HEAT SHIELD & REAR SILENCER OUTER CHROME PIPE	New	150.00	60.00
15	TO CHECK REAR WIRING HARNESS & FUNCTION	New	120.00	20.00
16	TO REPAIR ,PANEL BEAT ON REAR AFFECTED AREA ,CUT & WELD ON REPLACED PANEL RE-STRAIGHTEN ON REAR AFFECTED AREA & LABOUR TO REPLACE THE ABOVE PARTS	New	2,000.00	800.00
17	TO PUTTY ,PRIMER & SPRAY PAINT ON REAR BOOT LID ,REAR BUMPER ,REAR END PANEL,REAR AFFECTED LEFT & RIGHT FENDER ,REAR REVERSE SENSOR USING 2K PANEL	New	1,800.00	880.00
Gross Labour Cost (\$\$)			10,115.00	4,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >