

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21006656/KVF3E2

Date: 15/07/2021

REFERENCE

Insured/Claimant:	SKS United Pte Ltd	Policy No:	7210006124		
Date of Loss:	10/06/2021	Nature of Claim:	OD	Claim No:	5550324478SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF7468H		
Make & Model:	TOYOTA HIACE, 1.8 D SUPER GL DARK PRIME (A)	Engine No:	1KD2639116
Reg. Date:	13/02/2017 (Man. Year: 2016)	Chassis No:	KDH2015023825
Colour:	Silver	Odometer:	115224 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,089.22	3,192.30	1,896.92	37.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	870.00	330.00	27.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,289.22	4,062.30	2,226.92	35.41
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	5,689.22	3,462.30	2,226.92	39.14

INSPECTION

Date of Assignment: 14/06/2021

Date Inspected: 15/06/2021 Inspected At:

HWA SENG SPRAY PAINTING CO (HQ)
160 SIN MING DRIVE
#05-11 SIN MING AUTOCITY
SINGAPORE 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	756.60 FL	*756.60 FL
2	1		*LOGO EMBLEM	Necessary	66.20 FL	*66.20 FL
3	2		*BONNET HINGES	Repair	97.80 FL	*- FL
4	1		*FRONT GRILLE : TOP	Serviceable	191.50 FL	*- FL
5	1		*FRONT GRILLE : LOWER	Dented / Cut	330.80 FL	*330.80 FL
6	1		*FRONT GRILLE : INNER	Mtg Cracked	491.10 FL	*432.00 FL
7	1		*FRONT BUMPER	Buckled / Dented	487.10 FL	*487.10 FL
8	2		*HEADLAMP	Mtg Cracked	1,897.40 FL	*1,697.40 FL
9	1		*FRONT BUMPER REINFORCEMENT	Bent	304.40 FL	*272.00 FL
10	1		*SUPPORT PANEL	Repair	283.10 FL	*- FL
11	1		*BONNET LOCK	Repair	77.50 FL	*- FL
12	1		*AIR CON CONDENSER	Serviceable	1,216.10 FL	*- FL
13	1		*FRONT BUMPER TOWING COVER	Serviceable	26.20 FL	*- FL
14	1		*FRONT BUMPER LOWER GRILLE	Cracked	154.30 FL	*154.30 FL
15	1		*SIDE FOG LAMP COVER	Serviceable	62.40 FL	*- FL
16	1		*FRONT BUMPER RETAINER	Serviceable	193.10 FL	*- FL
17	1		*FRONT BUMPER BRACE PANEL	Repair	56.70 FL	*- FL
18	1		*NUMBER PLATE WITH CASING	Dented	70.00 FS	*45.00 FS
					Sub Total (S\$)	6,762.30 4,241.40
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,673.08 1,049.10
					Total Parts (S\$)	5,089.22 3,192.30

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL KNOCKING	New	500.00	400.00
2	SPRAY PAINTING	New	500.00	450.00
3	WIRE CHECKING	New	50.00	20.00
4	VACUUM & TOP UP AIR CON GAS	New	150.00	0.00
Gross Labour Cost (\$\$)			1,200.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >